

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21002658/UPA3Q2

Date: 14/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993724

Claimant
Vehicle No : CB7935K **Insured Vehicle No :** GBG5237R

Date of Loss: 25/02/2021 Nature of Claim: TP Claim No: 1744538273SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|---------------|
| Reg No: | CB7935K | | |
| Make & Model: | TOYOTA HIACE, 3.0 D DX (A) | Engine No: | 1KD2713903 |
| Reg. Date: | 11/07/2017 (Man. Year: 2017) | Chassis No: | KDH2010223200 |
| Colour: | Silver | Odometer: | 246094 km |
| Engine Capacity: | 2982 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 195 R15 | Rear Tyre Size: | 195 R15 |
| Front Left Side: | Michelin 6 mm | Rear Left Side: | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 5,498.90 | 1,981.37 | 3,517.53 | 63.97 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,270.00 | 1,340.00 | 930.00 | 40.97 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 7,768.90 | 3,321.37 | 4,447.53 | 57.25 |
| Approved Total (Overridden) (S\$) | | 2,650.00 | | |
| (S\$) | 7,768.90 | 2,650.00 | 5,118.90 | 65.89 |
| + GST 7.00/7.00% (S\$) | 543.82 | 185.50 | 358.32 | 65.89 |
| Nett Amount (S\$) | 8,312.72 | 2,835.50 | 5,477.22 | 65.89 |
| + Car Rental (4.0 x S\$120.00/day + 7.00% GST) (S\$) | | 513.60 | | |
| + Doc/Search Fee (S\$) | | 7.45 | | |
| Nett Liability (S\$) | | 3,356.55 | | |
| Global Sum Settlement (S\$) | | 3,300.00 | | |

INSPECTION

Date of Assignment: 26/02/2021

Date Inspected: 26/02/2021 Inspected At:

Stytech Auto Pte Ltd (HQ)
2 Kaki Bukit Ave 2 #02-30, Kaki Bukit
Autohub
Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------|---------------|------------|--------------|
| 1 | 1 | | *LEFT REAR FENDER | Dented / Bent | 1,436.70 F | *1,436.70 FL |
| 2 | 1 | | *LEFT TAILLAMP | Scratched | 455.70 F | *368.50 FL |
| 3 | 1 | | *LEFT REAR CORNER PANEL GARNISH | Repair | 129.60 F | *- FL |
| 4 | 1 | | *LEFT REAR BUMPER BRACKET | Not Necessary | 65.80 F | *- FL |
| 5 | 1 | | *REAR BUMPER | Cut | 450.70 F | *450.70 FL |
| 6 | 1 | | *REAR BUMPER CLIP | Necessary | 30.00 FS | *30.00 FS |
| 7 | 1 | | *LEFT REAR TYRE | Serviceable | 200.00 FS | *- FS |
| 8 | 1 | | *LEFT REAR RIM | Not Necessary | 200.00 FS | *- FS |
| 9 | 1 | | *LEFT REAR RIM CAP | Cut | 212.60 F | *212.60 FL |
| 10 | 1 | | *REAR AXEL SHAFT | Not Necessary | 1,883.20 F | *- FL |
| 11 | 2 | | *REAR AXEL SHAFT BEARING | Not Necessary | 197.40 F | *- FL |
| 12 | 2 | | *REAR AXEL SHAFT OIL SEAL | Not Necessary | 77.20 F | *- FL |
| 13 | 1 | | *REAR AXEL OIL | Not Necessary | 50.00 FS | *- FS |
| 14 | 1 | | *REAR LH MUFFLER | Grazed | 50.00 FS | *50.00 FS |
| 15 | 1 | | *REAR FENDER GLASS SEALANT | Necessary | 60.00 FS | *50.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---------------------------------------------------------|-----------------|-----------------|
| Sub Total (\$) | 5,498.90 | 2,598.50 |
| - List Item Discount on L Items 0.00/25.00% (\$) | 0.00 | 617.13 |
| Total Parts (\$) | 5,498.90 | 1,981.37 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|------------------------------------|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | ANT RUST PROOFING | New | 100.00 | 40.00 |
| 2 | CHECK WIRING | New | 80.00 | 20.00 |
| 3 | INTERIOR UPHOLSTERY & REMOVE SEAT | New | 250.00 | 100.00 |
| 4 | JACK AXEL BEARING | New | 120.00 | 0.00 |
| 5 | PANEL BEATING | New | 800.00 | 680.00 |
| 6 | PAINT WORK | New | 800.00 | 400.00 |
| 7 | REMOVE & FITTING REAR FENDER GLASS | New | 120.00 | 100.00 |
| Gross Labour Cost (\$\$) | | | 2,270.00 | 1,340.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >