

ASS. REC. BY:

REF:

CS/U0121002663/R19P3

7434

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMV 6427Tat Workshop m/s ETH2of 30, BUKIT BATOK CRESCENTInsured: UOI

Policy No. _____

Claims No. M12D14952102

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 117K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMV 6427T Yr Regn: 2020 / OCTType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HYUNDAI TLMSON FL 2106650 1999Colour: GREY A/C: Insured / Std / NI / NASp. Reading: 9839 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM4J3813MLU336718

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/60R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / NIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 12/02/21 D.O.I. 26/02/21Survey held at ETH2

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair Unit - TOK09/3/21 @ 10.42am Road Analised final fig \$2811.84, 4 days with Shah.
clad 6

Date/Time, File Pass to?

1) 06/3/21 ☐ : Prell. Report ☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: TPLump Sum / L&L: 2811.84Days Of Repair: 4Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation: _____

Photos _____

Others _____

TOTAL

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 26/02/2021

To : UNITED OVERSEAS INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTRENT000423

Accident Date : 12/02/2021

Vehicle No : SMV-6427-T

Make & Model : HYUNDAI TUCSON 2.0 GLS (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>List Item</u>			
1	REAR BUMPER <i>de /</i>	546.50 ✓	
1	REAR BUMPER LOWER <i>on /</i>	481.40 ✓	
1	REAR BUMPER SPONGE ? <i>X3VL</i>	402.80	
1	REAR BUMPER RETAINER LH ? <i>X3VL REC ✓</i>	45.50 ✓	
10	REAR BUMPER CLIPS <i>na /</i>	50.00 ✓	
1	REAR BUMPER REFLECTOR LH <i>scr /</i>	55.90 ✓	
1	REAR BUMPER OUTER SENSOR LH ? <i>X3VL</i>	269.00	
1	TAILGATE	RESTORE	
1	TAILGATE GARNISH LOWER <i>scr /</i>	695.70 ✓	

Date : 26/02/2021

To : UNITED OVERSEAS INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTRENT000423

Accident Date : 12/02/2021

Vehicle No : SMV-6427-T

Make & Model : HYUNDAI TUCSON 2.0 GLS (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	TAILGATE REFLECTOR LH <i>see</i>	89.10 ✓	
1	TAILGATE LOGO <i>see</i>	69.10 ✓	2102.30
1	EMBLEM - TUCSON <i>see</i>	69.10 ✓	20%
1	END PANEL RESTORE		1681.84
	Sub Total	2774.10	
	Discount 20% On Parts	(554.82)	
	Labour & Misc		
	LABOUR TO FACILITATE REPAIR	800.00 600 ✓	
	TO RESPRAY AFFECTED AREAS	800.00 500 ✓	
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00 ✓	1130

Date : 26/02/2021

To : UNITED OVERSEAS INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTRENT000423

Accident Date : 12/02/2021

Vehicle No : SMV-6427-T

Make & Model : HYUNDAI TUCSON 2.0 GLS (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	RUST PROOFING	50.00	Xan
	Sub Total	1680.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1681.84
1130.00
2811.84

Remarks:

4 days - p/p / Resurvey before paint

SUB TOTAL

GST 7.0 %

272.95

TOTAL

4,172.23

Surveyor's name:

Rasul - Hp 90010068

Principal's name:

ETHOZ Group Ltd

Survey Date & Time:

26/02/2021 @ 1630