

SLD26566. 2016 June.
 TP MS16. Toyota Estima. 2362cc
 Ximo Chun. ACR500192964

Rear Bumper	Distorted	789.40 ✓
Rear Bumper Clips	na	30(SN) ✓
Rear Bumper Side Holder	x02 ^{LH} 2nd	65 X 2 = 130 65
Rear Bumper Reflector LH.	could	61.10 ✓
Rear End Panel	Dented	755.40 ✓
Rear End Panel Top Garnish	Dehd	260.50 ✓
Rear End Panel Top Garnish Clips	Dec	20(SN) ✓
Rear End Panel Lower Garnish	Dehd	253.60 ✓
Rear End Panel Lower Garnish Clips	na	20(SN) ✓
Reverse Sensor	Damaged	280(SN) 200(SN)
Tailgate	Dented	1406.90 ✓
Tailgate Lock	Damaged	328.90 ✓
Tailgate Weatherstripe	na	299.80 x
Tailgate Glass Moulding	na	118.50 ✓
Tailgate Glass Sealant	na	60(SN) ✓
Toyota Logo	na	70.40 ✓
Estima Wordmark	na	65 ✓

SLD2656G.

Aercas Wording.	new	68.80	✓
Reer LH Fender Inner Trim Board	Deland	658.20	✓
Reer LH Fender Inner Trim Board clips.	new	30(SN)	✓
Floor Panel.	Pegs	1048.50	+
Floor Panel Surround Trim	MP m	556.0	+
Floor Panel Surround Trim Clips.	MP m	50(SN)	+
Floor Panel Top Cover.	Deland	589.90.	✓

Panel Beating	1400	1000
Spray Painting.	1200	900
Wiring.	50	30
To spray tuft coat	150	80
To remove reverse sensor	100	50
To remove rear camera.	100	50
To remove upholstery.	150	80
To transfer tailgate fittings.	150	80
To remove tailgate g/ings	180	120.

hist: 5497.60

Labour: 2290

len 25%: 4123.20

Total: 6873.20

SIN: 360

L/S: 5.5K.

06 Days.

5500

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: