



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGV 8343J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	2,250.00	-
1	FRONT BUMPER SIDE RETAINER	NOT NECESSARY	88.00	-
1	FRONT BUMPER SIDE BRACKET	NOT NECESSARY	64.50	-
	LESS 10% DISCOUNT		-240.25	-
			2,162.25	-
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT BUMPER SENSOR (SN)	SHORT CIRCUIT	250.00	215.00
			250.00	215.00
	<u>LABOUR</u>			
	TO TUFF COAT AFFECTED AREAS.	NOT NECESSARY	180.00	-
	TO RESPRAY AFFECTED AREAS.		1,400.00	200.00
	TO RENEW DAMAGED PARTS,STRAIGHTEN AND REPAIR FRONT CHASSIS MEMBER AND ALIGNED ALL PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		1,400.00	300.00
	TO POLISH AND COATING FOR NEW PAINT.	NOT NECESSARY	1,200.00	-
	TO REMOVE AND REPLACE FRONT SENSOR.		150.00	60.00
			4,330.00	560.00
	GRAND TOTAL		6,742.25	775.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			600.00

Report Ref No. CS3/AIG20014717/Btq2-1

LIM TEOW GUAN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.