Vehicle Number: SGV8343J

SPARE PARTS

QTY	PARTS DESCRIPTION		CONDITION		Workshop Estimation (S\$)		Our Revised Estimation (S\$)	
1 pc	List Items Front bumper Repair Front bumper side retainer Nn Front bumper side bracket Nn		bent bent hent	555	× 2,250.00 × 88.00 × 64.50	\$ \$	1015-01 2,250.00 (- 25-00 88.00 N	
		Discount	10.00%	\$ \$ \$	240.25	\$ \$	240.25	
/ehicle Number: SGV8343J SPARE PARTS		•		@ 10%	1040:00			
QTY	PARTS DESCRIPTION		CONDITION	Workshop Estimation (S\$)		Our Revised Estimation (S\$)		
1 pc	Special Nett Items Front bumper sensor		electronically shocked	\$	250.00	\$	215.80 250.00 50	
			Special Nett Sub-Total	\$	250.00	\$	250.00	
			Spare Parts Total	\$	2,412.25	\$	2,412.25	
							215.00	

LABOUR COST

S/No	JOB DESCRIPTIONS		77 Barrier 19 19 19 19 19 19 19 19 19 19 19 19 19	Vorkshop stimation (S\$)	Our Revised Estimation (\$\$)		
		Spare PartsTotal co	f \$	2,412.25	\$	2,412.25	
1	To tuff coat affected areas		\$	180,00	\$	150.00 NA	
2	To respray affected areas	200	\$	1,400.00	\$ 400 00	1,200.00	
3	To renew damaged parts, straighten ar and aligned all parts	and repair front chassis member	\$	1,400.00	\$ 600.00	1,200.00	
4	To polish and coating for new paint	* coating invoice Nn	\$.	1,200.00	\$ 400 00	1,200.00	
5	To remove and replace front sensor	Required	\$	150.00	\$ 60.00	120.00	
		Tota	\$	6,742.25	\$	6,282.25	
	The repairer has agreed to undertake the r Sum Basis. We have further adjusted the a	epair under a part by part					
	Sum Repair of:	amount to a part by part	\$	5,500.00			
	tone & SURJER			6			
	Fong Kok Heng Qualified Appraiser	PAI	RTS	936 •	60		
		5	N				
		LP	BOUR	Charles and the second			
		@ 200	70	2611 522			
				2088.	80		

4/3 2100/2

Repair days 4