

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21002668/GPS3Q2
Date: 03/01/2022**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MCV0007235
Claimant Vehicle No :	SMG7596K	Insured Vehicle No :	GBJ9955J
Date of Loss:	24/02/2021	Nature of Claim:	TP
		Claim No:	MCV2021D0000873

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG7596K		
Make & Model:	TOYOTA SIENTA, 1.5 CVT ELEGANCE (A)	Engine No:	2NRX396910
Reg. Date:	31/12/2018 (Man. Year: 2018)	Chassis No:	MHFZ28H3000059827
Colour:	Orange	Odometer:	55876 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size:	195/50 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,207.00	4,776.50	2,430.50	33.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,668.18	7,325.18	1,343.00	15.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,875.18	12,101.68	3,773.50	23.77
+ GST 7.00/7.00% (S\$)	1,111.26	847.12	264.14	23.77

Nett Amount (S\$)	16,986.44	12,948.80	4,037.64	23.77
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
Nett Liability (S\$)		13,648.80		

INSPECTION

Date of Assignment: 26/02/2021

Date Inspected: 09/03/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Borneo Motors (S) Pte Ltd (Ubi)
17 Ubi Road 4
Singapore 408611

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Nov 2021)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 CVT ELEGANCE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG7596K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS
2	1		*COVER ,RR BUMPER ,L	Deformed	316.10 FS	*316.10 FS
3	1		*SUPPORT ,RR BUMPER S	Not Necessary	73.60 FS	*- FS
4	1		*RETAINER ,RR BUMPER	Not Necessary	70.50 FS	*- FS
5	1		*SUPPORT ,RR BUMPER S	Not Necessary	73.60 FS	*- FS
6	1		*RETAINER ,RR BUMPER	Not Necessary	70.50 FS	*- FS
7	10		*CLIPS	Necessary	41.00 FS	*41.00 FS
8	1		*EXTENSION ,RR BUMPER	Deformed	190.00 FS	*190.00 FS
9	1		*EXTENSION ,RR BUMPER	Not Necessary	129.10 FS	*- FS
10	1		*EXTENSION ,RR BUMPER	Not Necessary	129.10 FS	*- FS
11	1		*PLATE ,RR BUMPER NO	Not Necessary	20.80 FS	*- FS
12	1		*LAMP ASSY ,RR FOG	Not Necessary	234.30 FS	*- FS
13	1		*BRACKET ,FOG LAMP	Not Necessary	55.90 FS	*- FS
14	1		*PANEL SUB-ASSY ,BODY	Bent	433.60 FS	*433.60 FS
15	1		*PANEL SUB-ASSY ,LWR	Repair	696.30 FS	*- FS
16	1		*COVER ,DECK TRIM RR	Not Necessary	154.10 FS	*- FS
17	1		*PANEL SUB-ASSY ,BACK	Buckled	1,131.90 FS	*1,131.90 FS
18	1		*WEATHERSTRIP ,BACK D	Twisted	372.30 FS	*372.30 FS
19	1		*GLASS SUB-ASSY ,BACK	Necessary	1,029.30 FS	*1,029.30 FS
20	1		*LOCK ASSY ,BACK DOOR	Not Necessary	467.60 FS	*- FS
21	1		*STRIKER ASSY ,BACK D	Not Necessary	25.70 FS	*- FS
22	1		*FRONT BONNET EMBLEM	Necessary	72.20 FS	*72.20 FS
23	1		*PLATE BACK DOOR NAM	Necessary	35.50 FS	*35.50 FS
24	1		*PLATE BACK DOOR NAM	Necessary	53.20 FS	*53.20 FS
25	1		*ANTENNA ,ELECTRICAL	Necessary	72.00 FS	*72.00 FS
26	1		*GARNISH SUB-ASSY ,BA	Not Necessary	229.40 FS	*- FS
27	1		*BACK SENSOR (4R8,ORANGE ME)	Not Working	172.40 FS	*172.40 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*FRT W/SCREEN DAM KIT	Necessary	121.00 FS	*121.00 FS
29	2		*SIKA 182010 SIKA TACK GO (BLA)	Necessary	216.00 FS	*216.00 FS
30	1		*SIKA 207 G+P ADHESIVE PRIMER	Necessary	200.00 FS	*200.00 FS
31	1		*INSTALL REAR WINDSCREEN GLASS 3M SOLAR FILM	Necessary	290.00 FS	*290.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					7,207.00	4,776.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PLATINUM SHINEPRO & SHINEPER PANEL APPLICATION ON REAR ACCIDENT AREAS	New	183.18	183.18
2	DRILL HOLE & INSTALL REAR REVERSE SENSOR	New	180.00	180.00
3	CHECK LIGHTING & CONDUCT WATER LEAK TEST	New	180.00	180.00
4	REMOVE & INSTALL REAR COMPARTMENT CARPET GARNISH AND TRIMMING TO ASSIST REPAIR	New	360.00	360.00
5	REPLACE & INSTALL REAR WINDSCREEN GLASS	New	495.00	462.00
6	REMOVE & INSTALL REAR REVERSE CAMERA	New	180.00	180.00
7	TRANSFER & INSTALL COMPONENTS TO NEW TAILGATE	New	360.00	360.00
8	TO RESET ECU AND REPROGRAMME	New	180.00	180.00
9	REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS	New	3,600.00	2,880.00
10	RESPRAY JOB ON REAR ACCIDENT AFFECTED AREAS	New	2,950.00	2,360.00
Gross Labour Cost (S\$)			8,668.18	7,325.18

Report was unsubmitted during this print-out.

< END OF ESTIMATES >