

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

**Our File No:** CC3/AIG21002669/EVF3E2

**Date:** 19/03/2021

### REFERENCE

Insured/Claimant:	LEE BOON KIAT	Policy No:	7210002695	
Date of Loss:	26/02/2021	Nature of Claim:	OD	Claim No: 2152067966SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX6040P	Engine No:	3A92UKB2512
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AMH004893
Reg. Date:	21/01/2021 (Man. Year: 2020)	Odometer:	1179 km
Colour:	Red		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$66,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,465.81	3,220.95	244.86	7.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,440.00	1,575.00	1,865.00	54.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,905.81</b>	<b>4,795.95</b>	<b>2,109.86</b>	<b>30.55</b>
<b>- Excess (S\$)</b>	<b>300.00</b>	<b>300.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>6,605.81</b>	<b>4,495.95</b>	<b>2,109.86</b>	<b>31.94</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>462.41</b>	<b>314.72</b>	<b>147.69</b>	<b>31.94</b>
<b>Nett Amount (S\$)</b>	<b>7,068.22</b>	<b>4,810.67</b>	<b>2,257.55</b>	<b>31.94</b>

### INSPECTION

Date of Assignment:	26/02/2021	
Date Inspected:	26/02/2021 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	4.0 days	

**Adjuster:** CHEN TSUE YEE

**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*FACE, FR BUMPER	Dented	706.00 FL	*706.00 FL
3	1		*COVER, FR BUMPER	Crushed	12.00 FL	*12.00 FL
4	1		*GRILLE ASSY, RADIATOR	Cut	600.00 FL	*600.00 FL
5	1		*MARK, THREE-DIA	Necessary	54.00 FL	*54.00 FL
6	1		*GRILLE, FR UNDER	Not Necessary	90.00 FL	*- FL
7	1		*GARNISH, FR BUMPER, RH	Not Necessary	44.00 FL	*- FL
8	1		*COVER, FR BUMPER GRILLE	Not Necessary	157.00 FL	*- FL
9	1		*BRACKET, FR BUMPER SIDE, RH	Not Necessary	8.00 FL	*- FL
10	1		*AIR DAM, SIDE, FR RH	Not Necessary	19.00 FL	*- FL
11	1		*GARNISH, FR BUMPER SIDE	Cut	168.00 FL	*168.00 FL
12	1		*GARNISH, FR BUMPER SIDE	Broken	120.00 FL	*120.00 FL
13	1		*FENDER, FR RH	Dented	430.00 FL	*430.00 FL
14	1		*HEADLAMP ASSY, RH	Broken	1,706.00 FL	*1,706.00 FL
15	1		*REINFORCEMENT, FR BUMPER	Bent	293.00 FL	*293.00 FL
16	1		*PANEL, AIR GUIDE, RH (Supplementary)	Crushed	14.00 FL	*14.00 FL
17	8		*RIVET,FR BUMPER (Supplementary)	Necessary	32.00 FL	*32.00 FL
18	1		*EMBLEM ECO (Supplementary)	Necessary	17.00 FS	*17.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,490.00	4,172.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	1,024.19	951.05
Total Parts (\$\$)	3,465.81	3,220.95

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW FRT BUMPER & RHF FENDER. REPAIR / RE-ALIGN FRT SUPPORT PNL & BONNET	New	1,800.00	675.00
2	RESPRAY FRT BUMPER, RHF FENDER, FRT SUPPORT & BONNET	New	1,400.00	700.00
3	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
5	SUPPLY FRT NUMBER PLATE WITH CASING	New	50.00	50.00
6	APPLY ANTI CORROSION ON AFFECTED AREAS	New	40.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,440.00</b>	<b>1,575.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >