

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21002674/GS3Q2
Date: 15/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800028155
Claimant Vehicle No :	GBH3083A	Insured Vehicle No :	SJK6817U
Date of Loss:	17/02/2021	Nature of Claim:	TP
		Claim No:	2012426564SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH3083A		
Make & Model:	NISSAN NV350 MICROBUS, 2.5 4DR 5MT ABS (A)	Engine No:	YD25423526A
Reg. Date:	13/04/2018 (Man. Year: 2017)	Chassis No:	JN1MC2E26Z0008711
Colour:	Silver	Odometer:	35655 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,596.00	1,460.70	1,135.30	43.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	860.00	1,040.00	54.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,496.00	2,320.70	2,175.30	48.38
Approved Total (Overridden) (S\$)		1,800.00		

(S\$)	4,496.00	1,800.00	2,696.00	59.96
+ GST 7.00/7.00% (S\$)	314.72	126.00	188.72	59.96
Nett Amount (S\$)	4,810.72	1,926.00	2,884.72	59.96
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
Nett Liability (S\$)		2,246.00		

INSPECTION

Date of Assignment: 26/02/2021

Date Inspected: 26/02/2021

Inspected At:

BH Auto Services Pte Ltd (Sin Ming)
 Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117
 Singapore 575636

Estimated Period of Repair: 3.0 days

Adjuster: ACCUSER4**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	572.00 F	*572.00 FL
2	10		*BUMPER CLIPS	Not Necessary	55.00 F	*- FL
3	1		*FRONT RIGHT DOOR	Dented	535.00 F	*535.00 FL
4	1		*FRONT RIGHT DOOR REGISTRATION STICKER	Necessary	35.00 F	*35.00 FL
5	1		*FRONT HEADLAMP RH	Scratched	481.00 F	*481.00 FL
6	1		*FRONT RH FOG LAMP	Not Necessary	321.00 F	*- FL
7	1		*FRONT RH FOG LAMP BRACKET	Not Necessary	118.00 F	*- FL
8	1		*FRONT GRILLE	Not Necessary	479.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,596.00	1,623.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	162.30
Total Parts (S\$)	2,596.00	1,460.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS ,PANEL BEAT ,CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS (FRONT)	New	700.00	400.00
2	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES	New	700.00	400.00
3	PROVIDE SKILL LABOUR TO DISMANTLE AND TRANSFER DOOR AND WINDOW	New	200.00	60.00
4	PROVIDE SKILL LABOUR TO WHEEL ALIGNMENT	New	150.00	0.00
5	PROVIDE SKILL LABOUR TO CHECK UNDERCARRIAGE	New	150.00	0.00
Gross Labour Cost (S\$)			1,900.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >