

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBN 92L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	WINDSHIELD (CONSISTENT)	SCRATCHED	155.00	155.00
1	TOP FAIRING INNER PANELS (CONSISTENT)	SCRATCHED	170.00	115.00
2	FORK INNER TUBES (CONSISTENT)	TO REPAIR SEE LABOUR	440.00	-
2	FORK OUTER TUBES (CONSISTENT)	N/S CUT	480.00	240.00
1	FORK UNDER BRACKET (CONSISTENT)	NOT NECESSARY	225.00	-
1	FRONT SPORT RIM (CONSISTENT)	NOT NECESSARY	450.00	-
1	FRONT BRAKE DISC (CONSISTENT)	NOT NECESSARY	360.00	-
1	FRONT RIM SHAFT (CONSISTENT)	NOT NECESSARY	70.00	-
1	FRONT RIM BEARING (CONSISTENT)	NOT NECESSARY	42.00	-
2	SIDE MIRRORS (CONSISTENT)	O/S CUT	156.00	68.00
2	HANDLE -BAR (CONSISTENT)	O/S BENT	250.00	115.00
1	SET HANDLE -BAR ENDS (CONSISTENT)	NOT FITTED	70.00	-
2	HANDLE GRIP (CONSISTENT)	O/S TORN	80.00	40.00
1	STARTER SWITCH (CONSISTENT)	CRACKED	185.00	185.00
1	CLUTCH LEVER (SCRATCHED)	NOT CONSISTENT WITH THE IMPACT	42.00	-
1	BRAKE LEVER (CONSISTENT)	CUT	42.00	42.00
1	BRAKE MASTER PUMP (CONSISTENT)	CUT	250.00	250.00
2	FRONT SIGNALS (CONSISTENT)	O/S BROKEN	136.00	60.00
2	FRONT FOOTREST (CONSISTENT)	CUT	100.00	48.00
1	SET FRONT FOOTREST BRACKET (CONSISTENT)	NOT NECESSARY	580.00	-
1	BRAKE PEDAL (CONSISTENT)	NOT NECESSARY	45.00	-
1	REAR SIGNALS (O/S) (CONSISTENT)	CRACKED	100.00	60.00
1	REAR SEAT (TORN)	NOT CONSISTENT WITH THE IMPACT	258.00	-
1	EXHAUST ASSY (CONSISTENT)	TO REPAIR SEE LABOUR	1,580.00	-
1	EXHAUST PROTECTOR (CONSISTENT)	CUT	150.00	150.00
1	EXHAUST END COVER (CONSISTENT)	CUT	45.00	45.00
1	SET FAIRING COVER (CONSISTENT)	CRACKED	1,200.00	960.00
1	SET SIDE FAIRING MATT (CONSISTENT)	сит	220.00	140.00

Report Ref No. CC4/ASM21002676/Uga3q2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	SET REAR FOOTREST (CONSISTENT)	NOT NECESSARY	170.00	-
1	SET REAR FOOTREST BRACKET (CONSISTENT)	NOT NECESSARY	310.00	-
1	REAR RIM SHAFT (CONSISTENT)	NOT NECESSARY	78.00	-
	LESS 10% DISCOUNT		-843.90	-267.30
			7,595.10	2,405.70
	SPECIAL NETT ITEMS			
1	SET NUMBER PLATE (SN) (CONSISTENT)	SCRATCHED	28.00	10.00
2	FORK OILS (SN) (CONSISTENT)	NECESSARY	30.00	30.00
2	FORK OIL SEALS (SN) (CONSISTENT)	NECESSARY	56.00	56.00
1	SET STEERING CONE (SN) (CONSISTENT)	NECESSARY	95.00	60.00
1	FRONT TYPE (SN) (CONSISTENT)	NOT NECESSARY	250.00	-
1	E.R.P IU (CUT) (SN)	NOT CONSISTENT WITH THE IMPACT	180.00	-
1	SET FAIRING COVER STICKER (SN) (CONSISTENT)	NOT FITTED	800.00	-
			1,439.00	156.00
	<u>LABOUR</u>			
	TO PROVIDE TOWING .		50.00	50.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO RESPRAY PAINTING.		550.00	300.00
	TO PROVIDE BODY FRAME REPAIR.	NOT NECESSARY	380.00	-
	TO PROVIDE LABOUR.		480.00	250.00
			1,540.00	600.00
	GRAND TOTAL		10,574.10	3,161.70

RECOMMENDED COST OF LUMP SUM REPAIRS	2,500.00
(TO ITS PRE-ACCIDENT CONDITION)	·

Report Ref No. CC4/ASM21002676/Uga3q2

CHUA KANG SENG

**Licensed Appraiser**