

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21002678/APA3Q2**Date:** 18/02/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SLX6658U **Insured Vehicle No :** GBD1917D

Date of Loss: 06/02/2021 Nature of Claim: TP Claim No: 9019216272SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLX6658U**

Make & Model: BMW 316I, 1.6 AT D/AB 4DR ABS HID (A) Engine No: A514J555N13B16A

Reg. Date: 30/09/2013 (Man. Year: 2013) Chassis No: WBA3A12090J721339

Colour: Black Odometer: 129520 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17

Front Left Side: 6 mm Rear Left Side: 6 mm

Front Right Side: Acceieta 6 mm Rear Right Side: A199 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,008.00	1,374.30	2,633.70	65.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	910.00	640.00	41.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,558.00	2,284.30	3,273.70	58.90
Approved Total (Overridden) (S\$)		1,800.00		
Nett Amount (S\$)	5,558.00	1,800.00	3,758.00	67.61
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
(S\$)		2,040.00		
Liabe Amount (50.00%) (S\$)		1,020.00		
Global Sum Settlement (S\$)		1,020.00		

INSPECTION

Date of Assignment: 23/02/2021

Date Inspected: 23/02/2021 Inspected At: Advance Auto Garage
10 Kaki Bukit Road 2, #01-21 First East Centre
Singapore 417868

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR	Dented	1,373.00 F	*1,373.00 FL
2	1		*REAR RH DOOR WEATHERSTRIPE	Necessary	154.00 F	*154.00 FL
3	1		*REAR RH DOOR INNER TRIM BOARD	Not Necessary	988.00 F	*- FL
4	1		*REAR RH DOOR INNER TRIM BOARD CLIPS	Not Necessary	30.00 FS	*- FS
5	1		*FRONT RH DOOR	Repair	1,298.00 F	*- FL
6	1		*FRONT RH DOOR WEATHERSTRIPE	Not Necessary	165.00 F	*- FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					4,008.00	1,527.00
- List Item Discount on L Items 0.00/10.00% (S\$)					0.00	152.70
Total Parts (S\$)					4,008.00	1,374.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	600.00	300.00
2	SPRAY PAINTING	New	600.00	500.00
3	WIRING	New	50.00	30.00
4	TO TRANSFER DOOR FITTING (FRONT AND REAR)	New	300.00	80.00
Gross Labour Cost (\$\$)			1,550.00	910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >