



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 1123C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (CONSISTENT)	CUT	590.00	590.00
1	FRONT BUMPER BRACKET (CONSISTENT)	NOT NECESSARY	210.00	-
1	FRONT BUMPER SIDE RETAINER (CONSISTENT)	NOT NECESSARY	105.00	-
1	FRONT DOOR (CONSISTENT)	DENTED	1,570.00	680.00
1	FRONT DOOR INNER RUBBER (CONSISTENT)	CUT / TORN	203.80	203.80
1	FRONT DOOR SIGNAL LAMP (CONSISTENT)	CRACKED	98.10	98.10
1	FRONT STOP GARNISH (CONSISTENT)	CUT	199.10	199.10
1	CABIN FENDER (CONSISTENT)	CUT	210.00	210.00
2	PROCTER RUBBER BUSH @\$18.00 (CONSISTENT)	TORN	36.00	36.00
1	TYRE (CONSISTENT)	SERVICEABLE	299.80	-
1	RIM (CONSISTENT)	BENT / DISTORTED	410.00	410.00
1	KNUCKLE ARM (CONSISTENT)	NOT NECESSARY	599.80	-
1	KNUCKLE WHEEL BEARING ASSY (CONSISTENT)	NOT NECESSARY	391.00	-
1	KNUCKLE HUP (CONSISTENT)	NOT NECESSARY	388.00	-
1	ABSORBER (CONSISTENT)	NOT NECESSARY	290.00	-
2	REAR WHEEL FENDER @\$189.00 (CONSISTENT)	DENTED	378.00	378.00
	LESS 10% DISCOUNT		-	-280.50
			5,978.60	2,524.50
<u>SPECIAL NETT ITEMS</u>				
1	COMPANY STICKER (SN) (CONSISTENT)	NECESSARY / CUT	25.00	20.00
			25.00	20.00
<u>LABOUR</u>				
	TO CHECK WIRING & REMOVE & RENEW .		120.00	30.00
	TO ADJUST CAMBER CASTOR ALIGNMENT .		150.00	60.00
	TO REMOVE & REFIT REPAIR UNDERCARRIAGE DAMAGE AFFECTED AREA.	NOT NECESSARY	480.00	-
	TO REMOVE & RENEW TYRE & BALANCING .		60.00	40.00
	TO KNOCKING ,STAIGHTEN REPAIR & RENEW ALL ACCIDENT AFFECTED AREA.		800.00	600.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY PAINTING ON ALL ACCIDENT DAMAGE AFFECTED AREA.		900.00	600.00
			2,510.00	1,330.00
GRAND TOTAL			8,513.60	3,874.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,100.00

Report Ref No. CC4/ASM21002681/Dgs3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.