



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### General Details

Involving	TPVD TOYOTA (SGY3493B)
Date of Loss	19 February 2021
Time of Loss	15.40
Loss Description	SJR1166K (INSD) hit SGY3493B (TP) rear
Comment	<input type="text"/>

### Workshop Details

Total Rebate Amount	<input type="text" value="9454"/>
Nett Loss Amount	\$5,046.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	<input type="text" value="20"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Vehicle & Driver Details



Vehicle Registration#	SGY3493B	Purchase Date	<div>dd/mm/yyyy</div> <div></div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>13/07/2011</div> <div></div>
Mileage	<div>141089</div>	Age of Vehicle	9

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<div>2011</div>
Make	TPVD	<div>TOYOTA</div>
		<div></div>

### Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	ANG CHEE WEE	<div></div>
Date of Birth		<div>dd/mm/yyyy</div> <div></div>

Model CATEGORY	TOYOTA POLICY INFORMATION	COROLLA ALTIS 1.6 AU ASSESSMENT INFORMATION
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="MR053REE104120449"/>
Engine No		<input type="text" value="1ZRX110554"/>
Engine Capacity		<input type="text" value="1598"/>
Sum Insured		<input type="text" value="0"/>
Market Value		<input type="text" value="14500"/>

CATEGORY Age	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="dd/mm/yyyy"/> 
License Expiration Date		<input type="text" value="dd/mm/yyyy"/> 

CATEGORY	FNOL INFORMATION	POST SURVEY
Address	Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text"/> ▼
Gender	Unknown	<input type="text"/> ▼
Marital status	Unknown	<input type="text"/> ▼
Identification #	TBC	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Detailed Assessment

Inspection Date \*

26/02/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/  
Unnamed Driver  
Excess

0

### Condition of Vehicle at time of survey

General condition

Fair



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake  
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair



Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text" value="25"/>	Settlement%	<input type="text" value="100"/>

## Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

YesNo

Part Supplied by AXA

YesNo

Save







SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts










Add











Approve





Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR BOOT LID	Dented	0	750	No		25			562.5	Reviewing
<input type="checkbox"/>		0	1		REAR BOOT LOCK	Damaged	0	204.86	No		25			153.65	Reviewing
<input type="checkbox"/>		0	1		REAR "1.6 VVT-I" EMBLEM	Necessary	0	65.38	No		25			49.04	Reviewing
<input type="checkbox"/>		0	1		REAR BOOT 'COROLLA' EMBLEM	Necessary	0	57.68	No		25			43.26	Reviewing
<input type="checkbox"/>		0	1		REAR BOOT "ALTIS" EMBLEM	Necessary	0	54.68	No		25			41.01	Reviewing
<input type="checkbox"/>		0	1		REAR BOOT "VSC" EMBLEM	Necessary	0	64.1	No		25			48.08	Reviewing

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR BOOT "DUAL" EMBLEM	Necessary	0	65.38	No		25			49.04	Reviewing
<input type="checkbox"/>		0	1		REAR RH BOOT HINGES RH	Bent	0	184.31	No		25			138.23	Reviewing
<input type="checkbox"/>		0	2		REAR RXL BOOT LAMP ASSY	Cracked	0	397.46	No		25			596.19	Reviewing
<input type="checkbox"/>		0	2		REAR RXL TAIL LAMP ASSY	Cracked	0	419.5	No		25			629.25	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER	Damaged	0	515.64	No		25			386.73	Reviewing
<input type="checkbox"/>		0	1		REAR RH BUMPER REFLECTOR	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		REAR RH BUMPER SIDE HOLDER	Broken	0	194.42	No		25			145.82	Reviewing
<input type="checkbox"/>		0	1		REAR RH TOP BUMPER SUPPORT	Broken	0	195.01	No		25			146.26	Reviewing
<input type="checkbox"/>		0	1		REAR BOOT LOGO	Necessary	0	65.38	No		25			49.04	Reviewing

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR END PANEL	Damaged	0	680	No		25			510	Reviewing
<input type="checkbox"/>		0	1		REAR END PANEL GARNISH	Damaged	0	145	No		25			108.75	Reviewing
<input type="checkbox"/>		0	1		REAR RH FENDER	Damaged	0	917	No		25			687.75	Reviewing
<input type="checkbox"/>		0	1		REAR EXHAUST	Repair	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		REAR RH WHEEL HOUSE AIR DUCT	Damaged	0	89.1	No		25			66.83	Reviewing
<input type="checkbox"/>		0	1		REAR GLASS REPAIR KIT	Necessary	0	120	No		25			90	Reviewing
<input type="checkbox"/>		0	1		REAR BOOT RUBBER	Damaged	0	250	No		25			187.5	Reviewing
<input type="checkbox"/>		0	1		REAR DOOR RH INNER LOCK	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		REAR RH TAIL LAMP PANEL	Damaged	0	255.3	No		25			191.48	Reviewing
<input type="checkbox"/>		0	1		REAR DOOR RH FRAME W/STRIP	Serviceable	0	0	No		25			0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR BOOT FLOOR PANEL	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		SET REAR BUMPER CLIP	Necessary	0	50	No		25			37.5	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER SENSOR	Shorted	0	200	No		25			150	Reviewing
<input type="checkbox"/>		0	1		TOWING FEE	Necessary	0	60	No		25			45	Reviewing







Labour



Add

Approve

Deny

Submit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		REAR GLASS REMOVE & REFIT	0	120	0	0	Reviewing	
<input type="checkbox"/>		0		REAR EXHAUST REMOVE & REFIT & REPLACE	0	30	0	0	Reviewing	
<input type="checkbox"/>		0		REAR BOOT INTERIOR REMOVE & REFIT	0	60	0	0	Reviewing	
<input type="checkbox"/>		0		ANTI RUST	0	40	0	0	Reviewing	
<input type="checkbox"/>		0		WIRING FEE	0	30	0	0	Reviewing	
<input type="checkbox"/>		0		RESPRAY PAINTING DAMAGE AREAS	0	1400	0	0	Reviewing	

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		TO REPAIR ACC DAMAGE AREAS	0	1350	0	0	Reviewing	
<input type="checkbox"/>		0		REAR BUMPER SENSOR REMOVE & REPLACE	0	30	0	0	Reviewing	



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>	0	DAYS OF REPAIR : 9 DAYS	Reviewing		0		



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount

\$0.00

Adjusted Claim Amount

\$8,172.91

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts	\$0.00	\$5,112.91
Labour	\$0.00	\$3,060.00

Submit for Review



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	FINAL LUMP SUM	Reviewing	5000		



Submit for Review