

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21002710/AGA3Q2**Date:** 28/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070007026
Claimant Vehicle No :	SLZ1402M	Insured Vehicle No :	SLC8588K
Date of Loss:	18/02/2021	Nature of Claim:	TP
		Claim No:	1426276693SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ1402M	Engine No:	CHZ435247
Make & Model:	AUDI A3, 999cc TFSI S TRONIC (LED) (A)	Chassis No:	WAUZZZ8V6J1055658
Reg. Date:	24/04/2018 (Man. Year: 2018)	Odometer:	113543 km
Colour:	Grey		
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,797.52	10,116.86	5,680.66	35.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,570.00	1,710.00	860.00	33.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,367.52	11,826.86	6,540.66	35.61
Approved Total (Overridden) (S\$)		9,400.00		
Nett Amount (S\$)	18,367.52	9,400.00	8,967.52	48.82
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	26/02/2021		
Date Inspected:	26/02/2021	Inspected At:	T & C Automotive (HQ) 1 KAKI BUKIT AVE 6,, #01-49, AUTOBAY Singapore 417883
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	3,404.00 F	*3,404.00 FL
2	1		*BOOT LID WEATHERSTRIP	Cut	205.00 F	*205.00 FL
3	1		*BOOT LID LOCK	Damaged	189.00 F	*189.00 FL
4	1		*BOOT LID CATCH	Not Necessary	49.60 F	*- FL
5	2		*BOOT LID REFLECTOR	Cut	1,754.00 F	*1,754.00 FL
6	1		*BOOT LID A3 EMBLEM	Necessary	98.80 F	*98.80 FL
7	1		*BOOT LID TFSI EMBLEM	Necessary	98.80 F	*98.80 FL
8	1		*BOOT LID AUDI LOGO	Necessary	137.50 F	*137.50 FL
9	2		*BOOT LID DAMPER	Not Necessary	103.50 F	*- FL
10	1		*BOOT LID TRIMBOARD	Not Necessary	306.50 F	*- FL
11	10		*BOOT LID TRIMBOARD CLIP	Not Necessary	50.00 F	*- FL
12	1		*TAIL LAMP	N/S Cracked	1,754.00 F	*877.00 FL
13	1		*REAR BUMPER	Deformed	1,944.00 F	*1,944.00 FL
14	10		*REAR BUMPER CLIP	Necessary	50.00 F	*50.00 FL
15	2		*REAR BUMPER SIDE RETAINER	Necessary	132.40 F	*132.40 FL
16	2		*REAR BUMPER REFLECTOR	Not Necessary	81.40 F	*- FL
17	1		*REAR BUMPER CENTER BRACKET (NPA)	Not Necessary	0.00 F	*- FL
18	1		*REAR BUMPER REINFORCEMENT	Bent	602.50 F	*602.50 FL
19	1		*REAR BUMPER FOAM (NPA)	Not Necessary	0.00 F	*- FL
20	1		*REAR BUMPER PAD	Cut	237.00 F	*237.00 FL
21	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	42.60 F	*- FL
22	4		*REAR PARKING SENSOR	Damaged (2 PCS ONLY)	447.92 F	*223.96 FL
23	2		*REAR LICENSE PLATE LAMP	Not Necessary	101.00 F	*- FL
24	2		*REAR FENDER INNER TRIM	Not Necessary	239.50 F	*- FL
25	20		*REAR FENDER INNER TRIM CLIP	Not Necessary	100.00 F	*- FL
26	1		*REAR END PANEL	Dented	1,092.50 F	*1,092.50 FL
27	1		*REAR END PANEL GARNISH	Deformed	154.50 F	*154.50 FL
28	8		*REAR END PANEL GARNISH CLIP	Necessary	40.00 F	*40.00 FL
29	1		*SPARE TYRE PANEL	Repair	662.00 F	*- FL
30	1		*SPARE TYRE BOARD	Not Necessary	541.50 F	*- FL
31	1		*EXHAUST SILENCER	Not Necessary	720.00 F	*- FL
32	1		*REAR NUMBER PLATE W/CASING	Not Necessary	90.00 FS	*- FS
33	1		*REVERSE CAMERA	Not Necessary	368.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,797.52	11,240.96
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	1,124.10
Total Parts (\$\$)	15,797.52	10,116.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REWIRING	New	80.00	30.00
2	ANTI-RUST UNDERCOATING	New	90.00	80.00
3	PANEL BEATING CHARGES TO REMOVE AND REPLACE ,TO CUT AND WELD ,TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	1,200.00	800.00
4	PUTTY & SPRAY PAINTING ALL AFFECTED PARTS & AREAS	New	1,200.00	800.00
			Gross Labour Cost (\$\$)	2,570.00
				1,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >