

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21002711/GTF3E2

**Date:** 02/07/2021

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00039222002		
<b>Claimant Vehicle No :</b>	SG5064X	<b>Insured Vehicle No :</b>	GBC8234A		
Date of Loss:	11/02/2021	Nature of Claim:	TP	Claim No:	SNM21D200900/C02/THAMYL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SG5064X</b>	Engine No:	HIDDEN
Make & Model:	VOLVO B9TL, 9.4 D (A)	Chassis No:	YV3S4P92XGA176862
Reg. Date:	21/03/2016 (Man. Year: 2016)	Odometer:	244768 km
Colour:	Green		
Engine Capacity:	9364 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	275/70R22.5	Rear Tyre Size:	275/70R22.5(D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	33.50	33.50	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	592.00	350.00	242.00	40.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>625.50</b>	<b>383.50</b>	<b>242.00</b>	<b>38.69</b>
<b>+ GST 7.00/7.00% (S\$)</b>	43.79	26.85	16.94	38.68
<b>Nett Amount (S\$)</b>	<b>669.29</b>	<b>410.35</b>	<b>258.94</b>	<b>38.69</b>

### INSPECTION

Date of Assignment:	10/03/2021		
Date Inspected:	02/03/2021	Inspected At:	SBS Transit Ltd (YCK) 3 Yio Chu Kang Crescent Singapore 786010
Estimated Period of Repair:	2.0 days		

**Adjuster:** XING GUO QIANG

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 02 Jul 2021)	
Parts:	N/A	VOLVO B9TL 9.4 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SG5064X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*SPRAY PAINT GREEN	Necessary	16.00 F	*16.00 F
2	1		*PUTTY KANDLE 2.5L	Necessary	17.50 F	*17.50 F
F=Franchise part.						
Total Parts (S\$)					33.50	33.50

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CONTRACTOR LABOUR COST	New	400.00	350.00
2	WORKSHOP ADMIN COST	New	192.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>592.00</b>	<b>350.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >