

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG21002719/R1PS3Q2

**Date:** 29/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993738

**Claimant**  
**Vehicle No :** SLR9650C **Insured Vehicle No :** GBE1186R

Date of Loss: 25/02/2021 Nature of Claim: TP Claim No: 8031222194SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLR9650C</b>		
Make & Model:	VOLKSWAGEN GOLF, 1.4 TSI (A7) (5G13GZ)	Engine No:	CZC159549
Reg. Date:	31/08/2017 (Man. Year: 2016)	Chassis No:	WVWZZZAUZHW114519
Colour:	Blue	Odometer:	100211 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,193.36	2,214.39	2,978.97	57.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,320.00	4,040.00	3,280.00	44.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>12,513.36</b>	<b>6,254.39</b>	<b>6,258.97</b>	<b>50.02</b>
<b>+ GST 7.00/7.00% (S\$)</b>	875.94	437.81	438.13	50.02
<b>Nett Amount (S\$)</b>	<b>13,389.30</b>	<b>6,692.20</b>	<b>6,697.10</b>	<b>50.02</b>
<b>+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)</b>		428.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>7,127.65</b>		

### INSPECTION

Date of Assignment: 03/03/2021

Date Inspected: 03/03/2021 Inspected At: Volkswagen Group Singapore Pte Ltd  
247 ALEXANDRA ROAD  
Singapore 159934

Estimated Period of Repair: 4.0 days

**Adjuster:** MOHD RASUL

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED FRT BUMPER	Scratched	1,247.94 FS	*1,247.94 FS
2	1		*SENSOR BRACKET	Necessary	14.51 FS	*14.51 FS
3	2		*SENSOR BRACKET	Necessary	29.02 FS	*29.02 FS
4	1		*SENSOR BRACKET	Necessary	14.51 FS	*14.51 FS
5	1		*2K-PLASTIC ADHESIVE	Necessary	78.91 FS	*78.91 FS
6	1		*BONDING AGENT FOR PLASTIC	Necessary	62.81 FS	*62.81 FS
7	1		*GUIDE PIECE RHF SIDE BRACKET	Serviceable	21.92 FS	*- FS
8	1		*RETAINER FOR SPOILER SATI	Serviceable	196.53 FS	*- FS
9	1		*IMPACT BEAM REINFORCEMENT	Serviceable	635.13 FS	*- FS
10	1		*FENDER RHF	Repair	623.70 FS	*- FS
11	1		*CROSS SUPPORT RHF FENDER BRACKET	Serviceable	33.22 FS	*- FS
12	2		*RIVETTED CAP NUT	Serviceable	4.56 FS	*- FS
13	1		*ALLOY WHEEL ALUMINIUM SHI (Not Necessary)	Not Consistent With The Impact	1,460.49 FS	*- FS
14	1		*RUBBER VALVE	Serviceable	3.42 FS	*- FS
15	1		*TWIN HALOGEN HEADLAMPS RHF	Scratched	766.69 FS	*766.69 FS
F=Franchise part. S=SpcNett.						
<b>Total Parts (\$\$)</b>					<b>5,193.36</b>	<b>2,214.39</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	280.00
3	LABOUR	New	3,360.00	1,680.00
4	SPRAY PAINTING	New	3,200.00	1,600.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,320.00</b>	<b>4,040.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >