

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21002724/UGA3Q2
Date: 14/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800062494-01
Claimant Vehicle No :	YP962T	Insured Vehicle No :	SKA488R
Date of Loss:	30/05/2019	Nature of Claim:	TP
		Claim No:	8775517497SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP962T		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER3SDEB (CBU) (M)	Engine No:	4P10B97461
Reg. Date:	22/01/2016 (Man. Year: 2015)	Chassis No:	FEB21EA20035
Colour:	Orange	Odometer:	230871 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15 (D)
Front Left Side:	Austone 6 mm	Rear Left Side:	Austone 6/6 mm
Front Right Side:	Austone 6 mm	Rear Right Side:	Austone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	480.00	360.00	120.00	25.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	150.00	100.00	50.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	630.00	460.00	170.00	26.98
Approved Total (Overridden) (S\$)		350.00		

Nett Amount (S\$)	630.00	350.00	280.00	44.44
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		532.00		

INSPECTION

Date of Assignment: 01/03/2021

Date Inspected: 01/03/2021

Inspected At:

Liu's Brother Auto Engineering Workshop (HQ)
 BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT
 Singapore 417883

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WHEEL FENDER	Deformed / Cracked	480.00 F	*480.00 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	480.00 480.00
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00 120.00
					Total Parts (\$\$)	480.00 360.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	150.00	100.00
Gross Labour Cost (\$)			150.00	100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >