

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21002727/AGA3Q2
Date: 10/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900108954
Claimant Vehicle No :	GBJ7542E	Insured Vehicle No :	SMM4373A
Date of Loss:	28/02/2021	Nature of Claim:	TP
		Claim No:	9019495027SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ7542E		
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Engine No:	1KD2860058
Reg. Date:	14/08/2019 (Man. Year: 2019)	Chassis No:	JTFAT35Y70K213681
Colour:	White	Odometer:	92636 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,099.18	6,906.72	12,192.46	63.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,500.00	2,540.00	2,960.00	53.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,599.18	9,446.72	15,152.46	61.60
Approved Total (Overridden) (S\$)		7,500.00		

Nett Amount (S\$)	24,599.18	7,500.00	17,099.18	69.51
+ Loss of Use (9.0 x S\$100.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,407.45		

INSPECTION

Date of Assignment: 01/03/2021

Date Inspected: 08/03/2021

Inspected At:

Ishare Auto Pte. Ltd. (HQ)
 8 KAKI BUKIT AVENUE 4 #08-09 PREMIER @ KAKI BUKIT
 Singapore 415875

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	794.30 FL	*589.00 FL
2	1		*FRONT BUMPER BRACKET RH	Bent	302.90 FL	*265.00 FL
3	1		*FRONT BUMPER FOGLAMP GARNISH RH	Not Necessary	95.80 FL	*- FL
4	1		*HEAD LAMP (LED) RH	Cut	980.20 FL	*925.00 FL
5	1		*FRONT STEP PANEL GARNISH RH	Cut	302.50 FL	*302.50 FL
6	1		*FRONT DOOR RH	Dented	1,794.20 FL	*1,650.00 FL
7	1		*FRONT DOOR OUTER MOULDING RH	Not Necessary	125.31 FL	*- FL
8	1		*FRONT DOOR OUTER HANDLE RH	Cut	214.60 FL	*214.60 FL
9	2		*FRONT DOOR HINGE RH	Not Necessary	197.00 FL	*- FL
10	1		*FRONT DOOR WEATHERSTRIP RH	Cut	205.70 FL	*205.70 FL
11	1		*FRONT DOOR ARCH RUBBER RH	Cut	102.80 FL	*102.80 FL
12	1		*FRONT DOOR INNER LOCK RH	Not Necessary	316.90 FL	*- FL
13	1		*FRONT DOOR LOCK CATCH RH	Not Necessary	45.80 FL	*- FL
14	1		*FRONT DOOR INNER TRIM BOARD RH	Cracked	697.20 FL	*581.00 FL
15	1		*FRONT DOOR SPEAKER RH	Not Necessary	288.70 FL	*- FL
16	1		*FRONT WHEEL REAR MUDGUARD RH	Cut	186.70 FL	*186.70 FL
17	1		*FRONT LOWER ARM RH	Not Necessary	867.70 FL	*- FL
18	1		*FRONT KNUCKLE ARM BEARING RH	Not Necessary	245.60 FL	*- FL
19	1		*FRONT WHEEL HUB RH	Not Necessary	518.20 FL	*- FL
20	1		*FRONT SHOCK ABSORBER RH	Not Necessary	396.80 FL	*- FL
21	1		*SET FRONT GRILLE CLIP	Not Necessary	50.00 FS	*- FS
22	1		*SET FRONT BUMPER FOGLAMP GARNISH CLIP RH	Not Necessary	40.00 FS	*- FS
23	1		*FRONT STEP PANEL GARNISH CLIP (SET) RH	Necessary	50.00 FS	*20.00 FS
24	1		*FRONT DOOR PILLAR SEALANT RH	Not Necessary	150.00 FS	*- FS
25	1		*SET FRONT DOOR INNER TRIM BOARD CLIP RH	Necessary	60.00 FS	*30.00 FS
26	1		*FRONT DOOR LTA WITH PROTECTOR STICKER	Necessary	80.00 FS	*30.00 FS
27	1		*FRONT DOOR SPICE VILLAGE STICKER	Necessary	550.00 FS	*200.00 FS
28	1		*SET DASHBOARD CLIP	Not Necessary	150.00 FS	*- FS
29	1		*FRONT WHEEL TYRE RH	Not Necessary	350.00 FS	*- FS
30	1		*REAR BOX FRONT SIDE PILLAR COVER ALUMINIUM RH	Repair	1,800.00 FS	*- FS
31	1		*REAR BOX SLIDING DOOR RH	Dented	3,800.00 FS	*1,400.00 FS
32	1		*REAR BOX SLIDING STOPPER BRACKET RH	Bent	120.00 FS	*80.00 FS
33	1		*REAR BOX SLIDING DOOR RAILING RH	Dented	2,400.00 FS	*500.00 FS
34	1		*REAR BOX SLIDING DOOR LOCK RH	Bent	150.00 FS	*80.00 FS
35	1		*SET REAR BOX STICKER	Necessary	2,800.00 FS	*800.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*BRAKE OIL	Not Necessary	40.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					21,268.91	8,162.30
- List Item Discount on L Items 25.00/25.00% (\$)					2,169.73	1,255.58
Total Parts (\$)					19,099.18	6,906.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT WELD CUT ADJUST KNOCK	New	1,600.00	1,000.00
2	TO PUTTY ,SPRAY PAINT ,POLISH WAX	New	1,600.00	1,200.00
3	TO SPRAY TUFF COAT	New	250.00	80.00
4	WIRING BULB CHECKING	New	350.00	30.00
5	CONDUCT WATER TER LEAKAGE TEST	New	80.00	0.00
6	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	250.00	0.00
7	TRANFER FRONT DOOR MECHANISM RH	New	80.00	80.00
8	REFOCUS HEADLAMP BEAM	New	60.00	0.00
9	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	650.00	0.00
10	TO PRESS FRONT WHEEL BEARING	New	80.00	0.00
11	FOUR WHEEL ALIGNMENT	New	120.00	0.00
12	REMOVE AND REFIX REAR BOX SLIDING DOOR	New	200.00	150.00
13	TO CHECK DIAGNOSTIC OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (S\$)			5,500.00	2,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >