

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21002728/EQD3E2

Date: 25/03/2021

REFERENCE

Insured/Claimant:	SUA YAP LIEN	Policy No:	1900166165		
Date of Loss:	26/02/2021	Nature of Claim:	OD	Claim No:	7489968883SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP4447E		
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Engine No:	4J11BG3366
Reg. Date:	26/09/2019 (Man. Year: 2019)	Chassis No:	GF7W0601819
Colour:	Red	Odometer:	22420 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$105,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,062.00	6,383.23	3,678.77	36.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,740.00	3,820.00	920.00	19.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,802.00	10,203.23	4,598.77	31.07
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	14,502.00	9,903.23	4,598.77	31.71
+ GST 7.00/7.00% (S\$)	1,015.14	693.23	321.91	31.71
Nett Amount (S\$)	15,517.14	10,596.46	4,920.68	31.71

INSPECTION

Date of Assignment:	01/03/2021	
Date Inspected:	02/03/2021 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	7.0 days	

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE WITH FRAME	Cut	50.00 FS	*50.00 FS
2	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
3	1		*FACE, FR BUMPER	Crushed	863.00 F	*863.00 FL
4	1		*EXTENSION, FR BUMPER	Not Necessary	517.00 F	*- FL
5	1		*GARNISH, FR BUMPER, RH	Not Necessary	48.00 F	*- FL
6	1		*GARNISH, FR BUMPER, LH	Not Necessary	48.00 F	*- FL
7	1		*BRACKET, FR BUMPER SIDE, RH	Not Necessary	18.00 F	*- FL
8	1		*BRACKET, FR BUMPER SIDE, LH	Not Necessary	18.00 F	*- FL
9	1		*GARNISH, FR BUMPER SIDE	Broken	220.00 F	*220.00 FL
10	1		*GARNISH, FR BUMPER SIDE	Not Necessary	220.00 F	*- FL
11	1		*COVER, FR BUMPER	Crushed	361.00 F	*361.00 FL
12	1		*GARNISH, FR LICENSE PLATE	Not Necessary	23.00 F	*- FL
13	1		*REINFORCEMENT, FR BUMPER	Not Necessary	493.00 F	*- FL
14	1		*REINFORCEMENT, FR BUMPER	Dented	135.00 F	*135.00 FL
15	1		*REINF, FR BUMPER SIDE, RH	Bent	69.00 F	*69.00 FL
16	1		*REINFORCEMENT, FR BMPR SIDE	Not Necessary	22.00 F	*- FL
17	1		*REINF, FR BUMPER SIDE, LH	Bent	60.00 F	*60.00 FL
18	1		*COVER, FR BUMPER	Not Necessary	25.00 F	*- FL
19	1		*COVER, HEADLAMP SUPT PANEL	Not Necessary	50.00 F	*- FL
20	1		*GRILLE ASSY, RADIATOR	Broken	550.00 F	*550.00 FL
21	1		*BRACKET, RADIATOR GRILLE, LH	Not Necessary	13.00 F	*- FL
22	1		*LATCH, HOOD	Not Necessary	76.00 F	*- FL
23	1		*HOOD	Dented	980.00 F	*980.00 FL
24	1		*FENDER, FR LH	Dented	622.00 F	*622.00 FL
25	1		*SHIELD, FR WHEELHOUSE, LH	Not Necessary	164.00 F	*- FL
26	1		*PANEL, HEADLAMP SUPPORT, UPR	Dented	183.00 F	*183.00 FL
27	1		*PNL, HEADLAMP SUPT, UPR LH	Not Necessary	58.00 F	*- FL
28	1		*HEADLAMP ASSY, LH	Broken	1,948.00 F	*1,948.00 FL
29	1		*HEADLAMP ASSY, RH	Broken	1,948.00 F	*1,948.00 FL
30	10		*RIVET (Supplementary)	Necessary	50.00 F	*50.00 FL
31	10		*CLIPS (Supplementary)	Necessary	20.00 F	*20.00 FL
32	10		*CLIPS (Supplementary)	Necessary	30.00 F	*30.00 FL
33	1		*MOULDING, FR WHEEL ARCH, LH (Supplementary)	Necessary	160.00 F	*160.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	10,062.00	8,269.00
- List Item Discount on L Items 0.00/23.00% (S\$)	0.00	1,885.77
Total Parts (S\$)	10,062.00	6,383.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, BONNET, FRT FENDER LH, FRT SUPPORT PANEL. REPAIR FRT DOOR LH, FRT FENDER RH	New	2,250.00	1,800.00
2	REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR	New	100.00	0.00
3	SPRAY PAINT FOR FRT BUMPER, FRT FENDER RH & LH, BONNET, FRT SUPPORT PANEL, FRT DOOR LH	New	2,100.00	1,750.00
4	REMOVE & INSTALL FRT AIRDAM	New	100.00	80.00
5	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	APPLY SEALANT FOR ACCIDENT PORTION	New	40.00	40.00
Gross Labour Cost (\$\$)			4,740.00	3,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >