

Surveyor : STEVE LKK
 Claim : AIG OD
 DOA : 26.01.2021
 Emailed : 22.03.2021, 3.10pm
 Date Survey : 02.03.2021

VEHICLE NO : SMP 4447 E
 MODEL : MIT OUTLANDER 2.0
 WIP : 63492

Material	:	\$	<u>6,313.23</u>
Labour	:	\$	<u>3,890.00</u>
Sub-Total	:	\$	<u>10,203.23</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>9,903.23</u>
GST 7%	:	\$	<u>693.23</u>
Grand Total	:	\$	<u>10,596.46</u>
Finalise By/Date	:	<u>LOI / 22/03/2021</u>	

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 02/03/2021	<table> <tr> <td>Cust No/Name</td><td>KCV12158/SUA YAP LIEN</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMP4447E / 26/09/2019</td></tr> <tr> <td>Date In/Mileage</td><td>02/03/2021/ 18937</td></tr> <tr> <td>Chassis/Package</td><td>GF7W0601819 /DC17P</td></tr> <tr> <td>Engine No</td><td>4J11BG3366</td></tr> <tr> <td>Make/Model</td><td>MIT/19MY OUTLANDER 2.0 STYLE(994)</td></tr> <tr> <td>Colour/Trim</td><td>P02 RED METALLIC / BK BLACK</td></tr> </table>	Cust No/Name	KCV12158/SUA YAP LIEN	Reg No/Reg Date	SMP4447E / 26/09/2019	Date In/Mileage	02/03/2021/ 18937	Chassis/Package	GF7W0601819 /DC17P	Engine No	4J11BG3366	Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)	Colour/Trim	P02 RED METALLIC / BK BLACK
Cust No/Name	KCV12158/SUA YAP LIEN														
Reg No/Reg Date	SMP4447E / 26/09/2019														
Date In/Mileage	02/03/2021/ 18937														
Chassis/Package	GF7W0601819 /DC17P														
Engine No	4J11BG3366														
Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)														
Colour/Trim	P02 RED METALLIC / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	22/03/2021/ 14:54	BLC	260 / AiTing	63492

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, BONNET, LH FRONT FENDER, FRONT SUPPORT PANEL, REPAIR LH FRONT DOOR, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				✓ 1800.00
E PNT98000 RESPRAY ON FRONT BUMPER, LH FRONT FENDER, BONNET, FRONT SUPPORT PANEL, LH FRONT DOOR, AND ALL OTHER AFFECTED AREAS TO THE SAME				✓ 1750.00
E PNT88000 REMOVE & INSTALL FRONT AIR DAM				✓ 80.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE				✓ 120.00
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTIONS				✓ 40.00
M SUNDRY SUNDRIES				✓ 20.00
S SPECIALISTJOB SUPPLY & REPLACE FRONT LICENSE PLATE WITH FRAME				✓ 50.00
X EXC EXCESS FOR OWN DAMAGE CLAIM				-300.00
X FACE,FR BUMPER	1.00	✓ 863.00	23.00	664.51
X GARNISH,FR BUMPER SIDE	1.00	✓ 220.00	23.00	169.40
X COVER,FR BUMPER	1.00	✓ 361.00	23.00	277.97
X REINFORCEMENT,FR BUMPER	1.00	? 135.00	23.00	103.95
X REINF,FR BUMPER SIDE,RH	1.00	? 69.00	23.00	53.13
X REINF,FR BUMPER SIDE,LH	1.00	? 60.00	23.00	46.20
X GRILLE ASSY,RADIATOR	1.00	✓ 550.00	23.00	423.50
X HOOD	1.00	✓ 980.00	23.00	754.60
X FENDER,FR LH	1.00	✓ 622.00	23.00	478.94
X PANEL,HEADLAMP SUPPORT,UPR	1.00	✓ 183.00	23.00	140.91
X HEADLAMP ASSY,LH	1.00	✓ 1948.00	23.00	1499.96
X HEADLAMP ASSY,RH	1.00	✓ 1948.00	23.00	1499.96

PRO-FORMA INVOICE

Co Reg No : 1977014696

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 02/03/2021	Cust No/Name	KCV12158/SUA YAP LIEN
	Reg No/Reg Date	SMP4447E / 26/09/2019
	Date In/Mileage	02/03/2021/ 18937
	Chassis/Package	GF7W0601819 /DC17P
	Engine No	4J11BG3366
	Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)
	Colour/Trim	P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	22/03/2021/ 14:54	BLC	260 / AiTing	63492

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X RIVET,FR BUMPER	10.00	5.00	23.00	38.50
X CLIP,ENG ROOM COVER	10.00	2.00	23.00	15.40
X CLIP,RR BUMPER	10.00	3.00	23.00	23.10
X MOULDING,FR WHEEL ARCH,LH	1.00	160.00	23.00	123.20

Z TEXT

AIG OD CLAIM

DOA : 26.01.21

SURVEYOR STEVE LKK 02.03.21

POLICY NO : 1900166165

Pro Forma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	6,313.23	Nett	9,903.23
Labour	3,780.00	7% GST on	9903.23
Standard Menu	0.00		
Specialist Job	50.00		
Diagnostics Job	0.00	Total Payable	10,596.46
Sundry/Others	-240.00		
Total(w/o GST)	9,903.23		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.


INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SMP 4447 E**

<u>Materials</u>		<u>Cost (\$)</u>
1	Rivet (x10)	50.00 / nec
2	Clips (x10)	20.00 / nec
3	Clips (x10)	30.00 / nec
4	Moulding, Fr wheel arch, LH	160.00 / nec
Total		260.00
Less 23% discount		59.80
Total after discount		200.20
7% GST		14.01
Grand total		<u>\$ 214.21</u>

Thank You.

Yours faithfully



LOI AI TING
SENIOR OFFICER - ADMIN
MITSUBISHI SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

NO. SPR44444E

After you enter you will be able to see all the cars

2021.03.10

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	DBA-GF7W 2019MY

2/3

All DTCs

2021.03.10

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition				
	KOS/IMMO/Keyless	KOS_8A880020		No DTCs					
	OSS	OSS_9588000B		No DTCs					
	CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error					
	ACC/FCM	ACCSFCM_4B080000		Non-equipped System or Communication Error					
	Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error					
	EPB	EPB_4C080000		No DTCs					
	Gateway	GW_C1000000		Non-equipped System or Communication Error					
	FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error					
	BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error					
	BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error					