

## CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

lo : 1977014696	<b>ESTIMATE</b>	GST Reg No : MR		
Invoice Name & Address	Owner Name & Vehicle Info			
SUA YAP LIEN	Cust No/Name	KCV12158/SUA YAP LIEN		
	Reg No/Reg Date	SMP4447E / 26/09/201		
BLK 307 WOODLANDS AVENUE 1	Date In/Mileage			
#07-309 SINGAPORE 730307	Chassis No	GF7W0601819		
5111GAPORE /30307	Engine No	4J11BG3366		
Contact No	Make/Model	MIT/19MY OUTLANDER 2.0 STYLE (994)		
W S		POZ RED METALLIC / BK BLACK		

Account No	Terms	Date/Time Printed CSE	Operator		WIP No			
KCV12158	CRDVCH		442 / CocoLu		63492			
	CROTCH	Description of Goods / Serv		Qty	Unit Price	Disc%		nount
E PNT88000 RENEW FR	BUMPER,	BONNET, FRT FENDER LH, FR	2	450	-	1.	1800	2250.00
REPAIR FR E PNT88000	RT DOOR L	H, FRT FENDER RH	c chata)			2 <sup>3</sup>		100.0
REMOVE &		AIRCON CONDENSOR & RADIATO				(30) 2r	1750	2100.0
SPRAY PA	INT FOR F	RT BUMPER, FRT FENDER RH &	(H) BONNET SX 3	50		× .	70	
FRT SUPPO E PNT88000	ORT PANEL	, FRT, DOOR LH					80	100.0
REMOVE &	INSTALL	FRT AIRDAM	- n			1 V		30.
1 54900099	ING & FI	FCTRICAL SYSTEM		12/0	7		120.0	
10028901 TO CARRY	OUT DIAG	NOSTIC CHECK USING THE SCAN			7			120.
USING HI- I SUNDRY	SCAN PRO	TEST	* 1				2	40.
APPLY SEA	LANT FOR	ACCIDENT PORTION					CUT	50.
SUNDRY FRT NUMBE								20.
SUNDRY		*					_	20.
Sundry FACE, FR BU	IMDED /	CRU		1.00	863.00	00.00		863.
FYIFNIIIN	FR KUMPE	K .		1.00		00.00		517.
GARNISH F	BUMPER.	RH X A/M		1.00		00.00		48.
GARNISH, FR	BUMPER.			1.00		00.00		48.0
BRACKET, FF	BUMPER	CIDE DII - C'I		1.00		00.00		18.0
BRACKET, FF	BUMPER	CIOC III LA MILIO		1.00		00.00	/	18.0
GARNISH, FR	BUMPER	SIDE / CLA CHIMIC UK		1.00	220.00		/	220.0
GARNISH FR	RUMPER	SIDE ! X MAI		1.00	220.00		/	220.0
COVER FR F	SUMPER	CRY (Black)		1.00	361.00			361.0 23.0
GARNISH F	LICENSE	PLATE X NM		1.00		00.00		493.0
REINFORCE	MENT, FR E	SUMPER X A/AI		1.00	493.00		/	135.0
A REINFORCE				1.00	135.00	00.00	,	133.0

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



## CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI MOTORS

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

Co Reg No : 197701469G

SUA YAP LIEN

SINGAPORE 730307

#07-309

Contact No

Authorized signatory and company stamp

Invoice Name & Address

BLK 307 WOODLANDS AVENUE 1

**ESTIMATE** GST Reg No : MR-8500111-X Owner Name & Vehicle Info KCV12158/SUA YAP LIEN Cust No/Name / 26/09/201 SMP4447E Reg No/Reg Date Date In/Mileage

> GF7W0601819 Chassis No 4J11BG3366 Engine No

MIT/19MY OUTLANDER 2.0 STYLE (994) Make/Model PO2 RED METALLIC / BK BLACK Colour/Trim

Account No	Terms	Date/Time Printed	CSE	Operator	and the second s	WIP No		
KCV12158	CRDVCH	01/03/2021/ 13:35		442 / CocoLu		63492		
RCVIEI30	CKOTCH	Description of Goods	/ Services		Qty	<b>Unit Price</b>		Amount
M REINF, FR	RUMPER S				1.00	69.00	00.00	69.0
M REINFORCE	MENT ED	BMPR SIDE ! X NAI			1.00		00.00	22.0
		A 17			1.00		00.00	60.0
		JAIAI			1.00	25.00	00.00	25.0
4 00450 454	NI AMO CII	DT DANEL I X MM			1.00		00.00	50.0
M COVER,HEA M GRILLE AS:	CA DAULA	TOR / GR			1.00	550.00		550.0
BRACKET.R	ANTATOR (	GRILLE, LH ? X MM			1.00	13.00	00.00	13.0
LATCH, HOOL		NAI			1.00		00.00	76.0
1 HOOD /		**************************************			1.00	980.00		980.
FENDER, FR		00			1.00	622.00		622.
CUIEIN ED	WHEEL HOLL	JSE, LH X MM			$\Box^{1.00}$	164.00		164.
DANEL HEAD	I AMD SIID	PPORT, UPR	2570	F30 (	257.00	183.00	Account the second	183.
PNL, HEADLA	MD CHDT	UPR LH 1 X NA	$\Xi \Pi \Pi$	(   )	二 1 1 1 .0000	58.00	00.00	58.
HEADLAMP A	CCV IH		>) (५।।	1111110	71 (4.60)	1948.00	00.00	1948.
HEADLAMP A					1.00	1948.00	00.00	1948.
the R • To re • To di • Part • Thire	epairer of survey before splay damag prices are so party survey to the splant of the survey to the s	ultants hence notify the following: e/after spray painting led part(s) during resurvey subject to confirmation y is on a "Without Prejudice" basis	Steve CL	EXC	4mys 1 BC SM 1 mc - j			
• Sup is 90 onfirm & acce Signa Date:	oted, by/	em(s) must be resurveyed <u>and</u> approval from Insurance Compan Repairer	У		7% GST on	Nett 14542.00		14,542.0 1017.9

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.