

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21002734/T1VD3E2
Date: 02/06/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 30001623045
Claimant Vehicle No : SKC959M Insured Vehicle No : SLT1220C
Date of Loss: 25/02/2021 Nature of Claim: TP Claim No: 253919

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKC959M**
Make & Model: MERCEDES-BENZ A200, 1.3 AMG LINE (A) Engine No: 28291480244907
Reg. Date: 17/01/2020 (Man. Year: 2019) Chassis No: WDD1771872J138338
Colour: Grey Odometer: 14156 km
Engine Capacity: 1332 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18
Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,246.16	5,117.64	13,128.52	71.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,240.00	2,150.00	3,090.00	58.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,486.16	7,267.64	16,218.52	69.06
Approved Total (Overridden) (S\$)		5,800.00		
Nett Amount (S\$)	23,486.16	5,800.00	17,686.16	75.30

INSPECTION

Date of Assignment: 01/03/2021
Date Inspected: 08/03/2021 Inspected At: Xin Yun Auto Pte Ltd (kaki Bukit) (HQ)
8 Kaki Bukit Avenue 4, #05-23 Premier @ Kaki Bukit
Singapore 415875
Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Jun 2021)

Parts: 144 MERCEDES-BENZ A200 1.3 AMG LINE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKC959M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER ASSY	Deformed	2,250.00 F	*1,550.00 FL
2	2		*BUMPER SIDE RETAINER	Deformed	190.00 F	*190.00 FL
3	2		*BUMPER SIDE SPACER	Deformed	205.00 F	*205.00 FL
4	1		*BUMPER SENSOR LEFT	Not Working	250.00 F	*190.00 FL
5	1		*BUMPER SENSOR CENTER	Not Working	250.00 F	*190.00 FL
6	2		*SENSOR CASING	Necessary	100.00 F	*100.00 FL
7	1		*SWITCH MODULE CARRIER BASIC CARRIER	Not Necessary	325.00 F	*- FL
8	2		*SENSOR REAR SWITCHING MODULE	Not Necessary	750.00 F	*- FL
9	2		*REAR BUMPER SENSOR ELECTRIC CABLE	Not Necessary	400.00 F	*- FL
10	2		*SWITCH SENSOR	Not Necessary	500.00 F	*- FL
11	1		*EMBLEM	Necessary	165.85 F	*165.85 FL
12	1		*A200 LOGO	Necessary	158.36 F	*158.36 FL
13	1		*TAILGATE ASSY	Repair	2,500.00 F	*- FL
14	1		*TAILGATE LOCK	Not Necessary	185.00 F	*- FL
15	2		*TAILGATE HINGES	Repair	197.20 F	*- FL
16	2		*TAILGATE HINGES BRACKET	Repair	220.00 F	*- FL
17	1		*TAILLIGHT LEFT	Not Necessary	775.75 F	*- FL
18	1		*REINFORCEMENT	Bent	850.00 F	*585.00 FL
19	1		*REINFORCEMENT TOP COVER GARNISH	Cracked	325.00 F	*325.00 FL
20	1		*REAR BUMPER LOWER LIP	Not Necessary	180.00 F	*- FL
21	1		*SILVING LINING / LOWER CHROME	Cut	375.00 F	*375.00 FL
22	1		*LOWER TRIM / BLACK	Deformed	616.00 F	*450.00 FL
23	1		*EXHAUST SUPPORT SILVER CHROME	N/S Cut / O/S Not Necessary	553.00 F	*276.50 FL
24	1		*LOWER BUMPER UNDERCARRIAGE BOTTOM	Torn	225.00 F	*225.00 FL
25	12		*BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
26	10		*LOWER COVER CLIPS	Necessary	40.00 FS	*20.00 FS
27	10		*INSULATOR CLIPS	Not Necessary	30.00 FS	*- FS
28	6		*TAILGATE SEAL CLIPS	Not Necessary	50.00 FS	*- FS
29	8		*SUPPORT PANEL GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
30	1		*NUMBER PLATE WITH CASHING	Not Necessary	80.00 FS	*- FS
31	1		*REAR LIGHT	Not Necessary	2,200.00 F	*- FL
32	2		*REAR LIGHT	Not Necessary	2,200.00 F	*- FL
33	2		*REAR LIGHT SIDE BRACKET	Cracked	210.00 F	*210.00 FL
34	2		*REAR LIGHT SUPPORT	Cracked	250.00 F	*250.00 FL
35	1		*TAILGATE TOP GARNISH	Deformed	325.00 F	*185.00 FL
36	2		*REINFORCEMENT TOP COVER	Not Necessary	205.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	18,246.16	5,680.71
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	563.07
Total Parts (S\$)	18,246.16	5,117.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT AFFECTED AREA	New	1,500.00	700.00
2	TO PUTTY AND SPRAY PAINTING BEHIND PORTION	New	1,800.00	800.00
3	TO DISMANTLE BOTH TAILLIGHT, REPLACE THE TAILLIGHT CHECK WIRING AND FOCUS BEHIND HEADLAMP	New	150.00	30.00
4	TO APPLY ANTI RUST PROOFING TO FRONT AFFECTED AREA	New	200.00	30.00
5	TO REMOVE AND INSTALL FRONT UNDERCARRIAGE PARTS	New	150.00	0.00
6	TO BALANCE THE WHEEL	New	80.00	0.00
7	TO CONDUCT WHEEL ALIGNMENT	New	120.00	0.00
8	TO REMOVE AND INSTALL TAILGATE LOCK MECHANISM ASSY	New	100.00	50.00
9	TO REMOVE AND INSTALL REAR BUMPER SENSOR	New	120.00	30.00
10	TO CONDUCT CHASSIS ALIGNMENT	New	150.00	0.00
11	TO DISMANTLE THE TAILGATE INTERNAL TRIMS TO ASSIST THE REPAIR	New	120.00	60.00
12	CERAMIC COATING	New	250.00	250.00
13	PROGRAMMING / CODING	New	500.00	200.00
			Gross Labour Cost (\$\$)	5,240.00
				2,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >