



Xin Yun Auto Private Limited
辛运汽车服务有限公司
Tel: 6634 0858 Email: xinyunauto1@gmail.com
Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SKC959M Mercedes AMG Hybrid A200

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area	\$ 1,500.00
2	To putty and spray painting behind portion.	\$ 1,800.00
3	To dismantle both taillight, repalce the taillight check wiring and focus behind headlamp.	\$ 150.00
4	To apply anti rust proofing to front affected area.	\$ 200.00
5	To remove and install front undercarriage parts.	\$ 150.00
6	To balance the wheel.	\$ 80.00
7	To conduct wheel alignment.	\$ 120.00
8	To remove and install tailgate lock mechanism assy.	\$ 100.00
9	To remove and install rear bumper sensor.	\$ 120.00
10	To conduct chassis alignment.	\$ 150.00
11	To dismantle the tailgate internal trims to assist the repair	\$ 120.00

Total labour : \$ 4,490.00

Total parts 13,156.26
Total labour : 4,490.00
Total repair cost : 21,627.11