

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21002735/T1PA3Q2  
**Date:** 17/08/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700067886
<b>Claimant Vehicle No :</b>	SLJ9705X	<b>Insured Vehicle No :</b>	SLT4331X
Date of Loss:	23/02/2021	Nature of Claim:	TP
		Claim No:	0235117110SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLJ9705X</b>	Engine No:	PE20838581
Make & Model:	MAZDA 6, 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A)	Chassis No:	JM6GL1071H0104864
Reg. Date:	30/12/2016 (Man. Year: 2016)	Odometer:	52664 km
Colour:	Red		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,830.48	5,239.96	6,590.52	55.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,900.00	860.00	4,040.00	82.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,730.48</b>	<b>6,099.96</b>	<b>10,630.52</b>	<b>63.54</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,900.00</b>		

## Adjuster Report

	(S\$)	16,730.48	4,900.00	11,830.48	70.71
<b>+ GST 7.00/7.00% (S\$)</b>		1,171.13	343.00	828.13	70.71
<b>Nett Amount (S\$)</b>		<b>17,901.61</b>	<b>5,243.00</b>	<b>12,658.61</b>	<b>70.71</b>
	<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment: 01/03/2021

Date Inspected: 03/03/2021

Estimated Period of Repair: 4.0 days

Inspected At:

AP Automotive Services Pte Ltd (HQ)  
Blk 9006 Tampines Street 93, #01-202  
Singapore 528840

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (NPA)	Repair	0.00 FL	*- FL
2	1		*BONNET LOCK	Not Necessary	217.50 FL	*- FL
3	1		*BONNET LOCK CATCH	Not Necessary	85.90 FL	*- FL
4	1		*BONNET INSULATOR	Not Necessary	419.85 FL	*- FL
5	2		*BONNET HINGE L+R	Not Necessary	166.20 FL	*- FL
6	2		*BONNET STOPPER	Not Necessary	47.00 FL	*- FL
7	1		*HEADLAMP L+R	N/S Not Necessary / O/S Cut	6,751.80 FL	*3,375.90 FL
8	1		*HEADLAMP BRACKET L+R	N/S Not Necessary /O/SDeformed	125.60 FL	*62.80 FL
9	1		*FRONT GRILLE ASSY	Cracked	673.85 FL	*673.85 FL
10	1		*FRONT GRILLE TOP GARNISH	Not Necessary	456.20 FL	*- FL
11	2		*FRONT GRILLE CHROME L+R	Not Necessary	374.60 FL	*- FL
12	1		*FRONT GRILLE LOGO -MAZDA	Necessary	95.00 FL	*95.00 FL
13	1		*FRONT BUMPER	Deformed	1,232.75 FL	*1,232.75 FL
14	1		*FRONT BUMPER GRILLE	Not Necessary	89.65 FL	*- FL
15	1		*FRONT BUMPER FOG LAMP GARNISH RH	Deformed	105.00 FL	*105.00 FL
16	1		*FRONT BUMPER FOG LAMP CHROME RH	Necessary	102.60 FL	*102.60 FL
17	1		*FRONT BUMPER FOG LAMP INNER BRACKET RH (NPA)	Not Necessary	0.00 FL	*- FL
18	1		*FRONT BUMPER RETAINER RH	Necessary	31.50 FL	*31.50 FL
19	1		*FRONT BUMPER REINFORCEMENT BAR	Not Necessary	585.90 FL	*- FL
20	1		*FRONT BUMPER REINFORCEMENT BAR BRACKET (NPA)	Not Necessary	0.00 FL	*- FL
21	1		*FRONT BUMPER SPONGE	Not Necessary	110.65 FL	*- FL
22	1		*FRONT FENDER RH	Repair	389.20 FL	*- FL
23	1		*FRONT FENDER COWLING RH	Torn	161.35 FL	*161.35 FL
24	1		*FRONT SUPPORT PANEL	Cracked	511.60 FL	*511.60 FL
25	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	95.80 FL	*- FL
26	1		*WIPER WASHER TANK	Deformed	147.60 FL	*147.60 FL
27	2		*FRONT HORN L+R	Not Necessary	161.00 FL	*- FL
28	1		*FRONT ABSORBER RH (NPA)	Not Necessary	0.00 FL	*- FL
29	1		*FRONT LOWER ARM RH (NPA)	Not Necessary	0.00 FL	*- FL
30	1		*FRONT KNUCKLE RH (NPA)	Not Necessary	0.00 FL	*- FL
31	1		*FRONT KNUCKLE BEARING RH (NPA)	Not Necessary	0.00 FL	*- FL
32	1		*FRONT BEARING HUB RH (NPA)	Not Necessary	0.00 FL	*- FL
33	1		*FRONT RIM RH (NPA)	Not Necessary	0.00 FL	*- FL
34	1		*BONNET INSULATOR CLIPS	Not Necessary	100.00 FS	*- FS
35	1		*FRONT NUMBER PLATE	Not Necessary	120.00 FS	*- FS

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING ON AFFECTED AREAS	New	1,200.00	400.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,000.00	400.00
3	TO CHECK WIRING AND HEADLAMP FOCUS }	New	150.00	30.00
4	TO CHECK WIRING AND FOG LAMP FUNCTION }	New	150.00	0.00
5	TO RNR INNER TRIMS AND UPHOLSTERY	New	400.00	0.00
6	TO RNR UNDERCARRIAGE	New	250.00	0.00
7	TO RNR WHEEL ALIGNMENT	New	250.00	0.00
8	TO RNR TYRE AND WHEEL BALANCING	New	250.00	0.00
9	TO CHECK WATER LEAK	New	150.00	0.00
10	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
11	TO PERFORM RUST PROOFING	New	400.00	30.00
12	TO RNR HORN AND TEST FUNCTION	New	100.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>4,900.00</b>	<b>860.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >