

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21002738/GGA3Q2
Date: 05/07/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100488477
Claimant Vehicle No :	SHC8182U	Insured Vehicle No :	SDK7160U
Date of Loss:	26/02/2021	Nature of Claim:	TP
		Claim No:	4540855982SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC8182U	Engine No:	D4FDGU701221
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMGU090088
Reg. Date:	26/05/2016 (Man. Year: 2016)	Odometer:	616424 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,159.04	1,683.20	1,475.84	46.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,030.00	870.00	160.00	15.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,189.04	2,553.20	1,635.84	39.05
+ GST 7.00/7.00% (S\$)	293.23	178.72	114.51	39.05

Nett Amount (S\$)	4,482.27	2,731.92	1,750.35	39.05
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 01/03/2021

Date Inspected: 01/03/2021

Estimated Period of Repair: 3.0 days

Inspected At:

ComfortDeIGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: XING GUO QIANG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER W LIP & FOG LAMP C	Cut	1,052.20 FL	*1,052.20 FL
2	10		*BUMPER COVER CLIP	Necessary	22.00 FL	*22.00 FL
3	1		*BRKT ASSY -FR BPR UPR SIDE	*Check	44.80 FL	*- FL
4	1		*BRACKET -FR BUMPER SIDE RH	Deformed	24.60 FL	*24.60 FL
5	1		*PANEL -FENDER RH	Buckled	663.00 FL	*663.00 FL
6	1		*LAMP ASSY -HEAD RH	*Check	1,800.00 FL	*- FL
7	1		*CAP ASSY -WHEEL HUB	Cut	217.20 FL	*217.20 FL
8	1		*FRT FENDER ADVERTISEMENT LOGO RH	Necessary	100.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,923.80	2,079.00
- List Item Discount on L Items 20.00/20.00% (\$)	764.76	395.80
Total Parts (\$)	3,159.04	1,683.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	350.00	280.00
2	SPRAYPAINT ON AFFECTED AREA	New	550.00	500.00
3	CHECK ALL LIGHTING	New	50.00	30.00
4	ADJUST FRONT WHEEL ALIGNMENT	New	80.00	60.00
			Gross Labour Cost (\$)	870.00
			1,030.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >