



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FZ 4332H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SET FORK (CONSISTENT)	BENT	480.00	450.00
1	SET COVER (CONSISTENT)	CRUMPLED	520.00	450.00
1	REAR RACK (CONSISTENT)	CRUMPLED	120.00	70.00
1	BOX (CONSISTENT)	NO SUCH PARTS	180.00	-
1	RHS FRONT FOOT REST RUBBER (CONSISTENT)	CUT	80.00	80.00
1	FRONT FOOTREST BRACKET (CONSISTENT)	BENT	110.00	110.00
1	RHS PILLAR FOOTREST (CONSISTENT)	BENT	80.00	80.00
1	RHS PILLAR FOOTREST RUBBER (CONSISTENT)	MISSING	60.00	60.00
1	HANDLE BAR (CONSISTENT)	BENT	140.00	140.00
1	FORK UNDER BRACKET (CONSISTENT)	BENT	160.00	160.00
1	STEERING CONE BEARING (CONSISTENT)	NECESSARY	150.00	125.00
1	FRONT RIM BEARING (CONSISTENT)	JAMMED	100.00	40.00
	LESS 10% DISCOUNT		-218.00	-176.50
			1,962.00	1,588.50
	<u>LABOUR</u>			
	BODY FRAME RE-ALIGNMENT.		800.00	100.00
	FORK RE-ALIGNMENT.	NOT NECESSARY	380.00	-
	FRONT RIM RE-ALIGNMENT.	NOT NECESSARY	380.00	-
	LABOUR TO DISMANTLE AND ASSEMBLE PARTS.		800.00	210.00
	TOWING FEE.		80.00	80.00
			2,440.00	390.00
	GRAND TOTAL		4,402.00	1,978.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,500.00

Report Ref No. CC4/ASM21002742/Qga3q2

OI SUN PIN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.