

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21002743/ETD3E2

Date: 14/04/2021

REFERENCE

Insured/Claimant:	LAI CHEE HEN	Policy No:	1900108954		
Date of Loss:	28/02/2021	Nature of Claim:	OD	Claim No:	9019495027SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM4373A	Engine No:	G4FGKH738700
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416MK5047761
Reg. Date:	28/06/2019 (Man. Year: 2018)	Odometer:	26654 km
Colour:	Silver		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$80,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,925.20	5,643.20	1,282.00	18.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,870.00	6,340.00	1,530.00	19.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,795.20	11,983.20	2,812.00	19.01
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	14,495.20	11,683.20	2,812.00	19.40
+ GST 7.00/7.00% (S\$)	1,014.66	817.82	196.84	19.40
Nett Amount (S\$)	15,509.86	12,501.02	3,008.84	19.40

INSPECTION

Date of Assignment:	01/03/2021	
Date Inspected:	02/03/2021	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	15.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*PANEL ASSY-FRONT DOOR, LH	Dented	1,277.00 FL	*1,277.00 FL
3	1		*PANEL ASSY-REAR DOOR, LH	Dented	1,377.00 FL	*1,377.00 FL
4	1		*PANEL ASSY-QUARTER OUTER, LH	Dented	1,349.00 FL	*1,349.00 FL
5	1		*WHEEL ASSY-ALUMINIUM	Cut	926.00 FL	*926.00 FL
6	1		*PANEL-FENDER, LH	Dented	430.00 FL	*430.00 FL
7	1		*MOULDING ASSY-FRT DR FRAME, LH	Necessary	72.00 FL	*72.00 FL
8	1		*W/STRIP ASSY-FR DR BELT O/S LH	Not Necessary	80.00 FL	*- FL
9	1		*W/STRIP ASSY-FR DR SIDE LH	Not Necessary	102.00 FL	*- FL
10	1		*W/STRIP-FR DR BODY SIDE LH	Not Necessary	125.00 FL	*- FL
11	1		*W/STRIP-FR DR BELT I/S LH	Not Necessary	43.00 FL	*- FL
12	1		*BASE ASSY-FR DR O/S HANDLE	Not Necessary	52.00 FL	*- FL
13	1		*MOULDING ASSY-RR DR FRAME, LH	Necessary	50.00 FL	*50.00 FL
14	1		*W//STRIP ASSY-RR DR BELT O/S LH	Not Necessary	75.00 FL	*- FL
15	1		*W/STRIP ASSY-RR DR SIDE LH	Not Necessary	102.00 FL	*- FL
16	1		*W/STRIP-RR DR BODY SIDE LH	Not Necessary	112.00 FL	*- FL
17	1		*W/STRIP-RR DR BELT I/S LH	Not Necessary	39.00 FL	*- FL
18	1		*GUARD-REAR WHEEL, LH	Not Necessary	75.00 FL	*- FL
19	1		*GLASS ASSY-REAR WINDOW	Not Necessary	447.00 FL	*- FL
20	1		*SCALP-O/S RR VOEW MIRROR, LH	Not Necessary	39.00 FL	*- FL
21	1		*COVER-RR BUMPER	Broken	651.00 FL	*651.00 FL
22	1		*COVER-RR BUMPER LWR	Not Necessary	241.00 FL	*- FL
23	1		*COVER-RR BUMPER UNDER, LH	Not Necessary	33.00 FL	*- FL
24	1		*BRACKET ASSY-RR BPR SIDE UPR, L	Broken	25.00 FL	*25.00 FL
25	1		*BLACK TAPE-FR DR RR, LH	Necessary	13.00 FL	*13.00 FL
26	1		*BLACK TAPE-RR DR FR, LH	Necessary	13.00 FL	*13.00 FL
27	1		*BLACK TAPE-RR DR FRAME RR OTR	Necessary	8.00 FL	*8.00 FL
28	1		*GLASS & MOULDING ASSY-QUARTER (Supplementary)	Necessary	252.00 FL	*252.00 FL
29	1		*FILM-ANTI CHIPPING LH (Supplementary)	Necessary	27.00 FL	*27.00 FL
30	1		*MIRROR ASSY-OUTSIDE RR VIEW, LH (Supplementary)	Cut / Broken	559.00 FL	*559.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,644.00	7,049.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,718.80	1,405.80
Total Parts (\$\$)	6,925.20	5,643.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT LH FENDER, FRT LH DOOR, REAR LH DOOR, REAR LH FENDER, REAR BUMPER & AFFECTED AREA. REPAIR ON FRT BUMPER PANEL	New	3,600.00	2,400.00
2	PAINT WORK ON FRT BUMPER, FRT LH FENDER, FRT LH DOOR, REAR LH DOOR, REAR LH FENDER, REAR BUMPER & LH WING MIRROR COVER	New	2,450.00	2,180.00
3	TO TRANSFER FRT & REAR LH DOOR ATTACHMENT TO NEW PANEL	New	240.00	240.00
4	TO REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR	New	120.00	120.00
5	TO REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR	New	120.00	120.00
6	TO REMOVE & INSTALL FUEL TANK FOR FACILITATE REPAIR	New	400.00	400.00
7	REMOVE & INSTALL REAR WINDSCREEN GLASS	New	240.00	240.00
8	TO APPLY WINDSCREEN SEALANT	New	80.00	80.00
9	TO APPLY BODY SEALANT FOR FACILITATE REPAIR	New	80.00	80.00
10	PERFORM RUST PREVENTION	New	40.00	40.00
11	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
12	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
13	TO TRANSFER FRT LH RIM INCLUDING BALANCING	New	30.00	30.00
14	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
15	TO REMOVE & INSTALL REAR PARKING ASSIST	New	120.00	60.00
16	SUPPLY & REPLACE LH REAR QUARTER GLASS SOLAR FILM (Supplementary)	New	80.00	80.00
Gross Labour Cost (S\$)			7,870.00	6,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >