



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV10378/LAI CHEE HEN
	Reg No/Reg Date	SMM4373A / 28/06/201
	Date In/Mileage	02/03/2021/ 0
	Chassis No	KNAF3416MK5047761
	Engine No	G4FGKH738700
	Make/Model	KIA/CERATO 1.6 A SR SX G335
	Colour/Trim	4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	01/03/2021/ 14:47	QUK	282 / Kevin Leong	29721			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT LH FENDER, FRT LH DOOR, REAR LH DOOR, REAR LH FENDER, REAR BUMPER & AFFECTED AREA REPAIR ON FRT BUMPER PANEL								3600.00
E PNT98000 PAINT WORK ON FRT BUMPER, FRT LH FENDER, FRT LH DOOR, REAR LH DOOR, REAR LH FENDER, REAR BUMPER & LH WING MIRROR COVER								2450.00
E PNT88000 TO TRANSFER FRT & REAR LH DOOR ATTACHMENT TO NEW PANEL								240.00
E PNT88000 TO REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR								120.00
E PNT88000 TO REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR								120.00
A 13900099 TO REMOVE & INSTALL FUEL TANK FOR FACILITATE REPAIR								400.00
E PNT88000 REMOVE & INSTALL REAR WINDSCREEN GLASS								240.00
M SUNDRY TO APPLY WINDSCREEN SEALANT								80.00
M SUNDRY TO APPLY BODY SEALANT FOR FACILITATE REPAIR								80.00
M SUNDRY PERFORM RUST PREVENTION								40.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
M SUNDRY TO TRANSFER FRT LH RIM INCLUDING BALANCING								30.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment								120.00
E PNT88000								120.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV10378/LAI CHEE HEN
	Reg No/Reg Date	SMM4373A / 28/06/201
	Date In/Mileage	02/03/2021/ 0
	Chassis No	KNAF3416MK5047761
	Engine No	G4FGKH738700
	Make/Model	KIA/CERATO 1.6 A SR SX G335
	Colour/Trim	4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	01/03/2021/ 14:47	QUK	282 / Kevin Leong	29721		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
TO REMOVE & INSTALL REAR PARKING ASSIST							
M SUNDRY							50.00
SUNDRIES							
M	PANEL ASSY-FRONT DOOR,LH			1.00	1277.00	20.00	1021.60
M	PANEL ASSY-REAR DOOR,LH			1.00	1377.00	20.00	1101.60
M	PANEL ASSY-QUARTER OUTER,LH			1.00	1349.00	20.00	1079.20
M	WHEEL ASSY-ALUMINIUM			1.00	926.00	20.00	740.80
M	PANEL-FENDER,LH			1.00	430.00	20.00	344.00
M	MOULDING ASSY-FRT DR FRAME,LH			1.00	72.00	20.00	57.60
M	W/STRIP ASSY-FR DR BELT O/S LH			1.00	80.00	20.00	64.00
M	W/STRIP ASSY-FR DR SIDE LH			1.00	102.00	20.00	81.60
M	W/STRIP-FR DR BODY SIDE LH			1.00	125.00	20.00	100.00
M	W/STRIP-FR DR BELT I/S LH			1.00	43.00	20.00	34.40
M	BASE ASSY-FR DR O/S HANDLE LH			1.00	52.00	20.00	41.60
M	MOULDING ASSY-RR DR FRAME,LH			1.00	50.00	20.00	40.00
M	W/STRIP ASSY-RR DR BELT O/S LH			1.00	75.00	20.00	60.00
M	W/STRIP ASSY-RR DR SIDE LH			1.00	102.00	20.00	81.60
M	W/STRIP-RR DR BODY SIDE LH			1.00	112.00	20.00	89.60
M	W/STRIP-RR DR BELT I/S LH			1.00	39.00	20.00	31.20
M	GUARD-REAR WHEEL,LH			1.00	75.00	20.00	60.00
M	GLASS ASSY-REAR WINDOW			1.00	447.00	20.00	357.60
M	SCALP-O/S RR VIEW MIRROR,LH			1.00	39.00	20.00	31.20
M	COVER-RR BUMPER			1.00	651.00	20.00	520.80
M	COVER-RR BUMPER LWR			1.00	241.00	20.00	192.80
M	COVER-RR BUMPER UNDER,LH			1.00	33.00	20.00	26.40
M	BRACKET ASSY-RR BPR SIDE UPR,L			1.00	25.00	20.00	20.00
M	BLACK TAPE-FR DR RR,LH			1.00	13.00	20.00	10.40
M	BLACK TAPE-RR DR FR,LH			1.00	13.00	20.00	10.40
M	BLACK TAPE-RR DR FRAME RR OTR,			1.00	8.00	20.00	6.40

Confirm & accepted by

Nett 14,044.80
 7% GST on 14044.80 983.14
Total Payable 15,027.94

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.