10/18/21, 9:24 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21002748/UQF3N2

18/10/2021 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMHCSNA00001942000

Claimant Vehicle

FBL2076G

Insured Vehicle No:

SLW4122S

No:

Nature of

Date of Loss:

18/02/2021

TP Claim:

SNM21D201034/C02/CHUAKK

DESCRIPTION & IDENTIFICATION OF VEHICLE

FBL2076G Reg No:

KTM 350 EXC-F, 347cc Make & Model: Engine No:

0377520292 Reg. Date: 27/08/2012 (Man. Year: 2012) Chassis No: VBKEXA401DM277674

Colour: Black Odometer: 0 km

Engine Capacity: 347 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 120/70 ZR17 Rear Tyre Size: 160/60 ZR17 Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm Front Right Side: Rear Right Side: 0 mm 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		6,331.50	2,308.50	4,023.00	63.54
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,220.00	280.00	940.00	77.05
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	7,551.50	2,588.50	4,963.00	65.72
	Approved Total (Overridden) (S\$)		2,000.00		
	Nett Amount (S\$)	7.551.50	2.000.00	5.551.50	73.52

INSPECTION

Date of Assignment: 02/03/2021

Erofia Motor Trading Pte Ltd (KAKI BUKIT)

1 KAKI BUKIT AVE 6 #02-62 Date Inspected: 02/03/2021 Inspected At:

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 15 Oct 2021)

Parts: N/A KTM 350 EXC-F 347cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBL2076G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

1		*FORK TRIPLE CLAMP	Repair	2,220.00 FL	*-FL
1		*FRONT FENDER	Deformed	175.00 FL	*175.00 FL
1		*HANDLE-BAR	Repair	620.00 FL	*- FL
1		*BRAKE LEVER	Cracked	155.00 FL	*155.00 FL
1		*FUEL TANK SIDE COVER-R/H	Cracked	630.00 FL	*495.00 FL
1		*SET FRONT FOOTREST	Cut	420.00 FL	*420.00 FL
1		*BRAKE PEDAL	Not Necessary	360.00 FL	*- FL
1		*EXHAUST ASSY	Cut	1,700.00 FL	*1,200.00 FL
1		*AIR BOX COVER-R/H	Deformed	120.00 FL	*120.00 FL
1		*REAR FENDER	Repair	235.00 FL	*- FL
1		*FORK OILS	Not Necessary	50.00 FS	*- FS
1		*FORK OIL SEALS	Not Necessary	90.00 FS	*-FS
1		*SET STEERING CONE	Not Necessary	220.00 FS	*- FS
chise part.	. S=SpcNett.	L=ListItemDisc.			
			Sub Total (S\$)	6,995.00	2,565.00
		- List Item Discount on L Items 10.00/10.00% (S\$)		663.50	256.50
			Total Parts (S\$)	6,331.50	2,308.50
1111111	 chise part	 chise part. S=SpcNett.	*FRONT FENDER *HANDLE-BAR *BRAKE LEVER *FUEL TANK SIDE COVER-R/H *SET FRONT FOOTREST *BRAKE PEDAL *EXHAUST ASSY *AIR BOX COVER-R/H *REAR FENDER *FORK OILS *FORK OILS *SET STEERING CONE chise part. S=SpcNett. L=ListItemDisc.	*FRONT FENDER *HANDLE-BAR *BRAKE LEVER Cracked *FUEL TANK SIDE COVER-R/H *SET FRONT FOOTREST Cut *BRAKE PEDAL *EXHAUST ASSY Cut *AIR BOX COVER-R/H *REAR FENDER *FORK OILS *FORK OILS *FORK OIL SEALS Not Necessary *SET STEERING CONE Cut Not Necessary *SET STEERING CONE Not Necessary *SET STEERING CONE Cut *Cut *AIR BOX COVER-R/H Deformed *Repair *FORK OILS Not Necessary *SET STEERING CONE Not Necessary *SET STEERING CONE Cut *Sub Total (S\$) - List Item Discount on L Items 10.00/10.00% (S\$)	#RONT FENDER Deformed 175.00 FL #HANDLE-BAR Repair 620.00 FL #BRAKE LEVER Cracked 155.00 FL #FUEL TANK SIDE COVER-R/H Cracked 630.00 FL #SET FRONT FOOTREST Cut 420.00 FL #BRAKE PEDAL Not Necessary 360.00 FL #EXHAUST ASSY Cut 1,700.00 FL #AIR BOX COVER-R/H Deformed 120.00 FL #REAR FENDER Repair 235.00 FL #FORK OILS Not Necessary 50.00 FS #FORK OIL SEALS Not Necessary 90.00 FS #SET STEERING CONE Not Necessary 220.00 FS #SET STEERING CONE Not Necessary 90.00 FS #SET STEERING CONE Not Necessary 6,995.00 - List Item Discount on L Items 10.00/10.00% (\$\$) 663.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO CHECK WIRING AND RESET HEADLAMP FORCUSIN	G New	80.00	0.00
2	TO PROVIDE FRONT FORK REPAIR	New	280.00	80.00
3	TO CHECK BODY FRAME	New	380.00	0.00
4	TO PROVIDE LABOUR	New	480.00	200.00
		Gross Labour Cost (S\$)	1,220.00	280.00
	Report was unsubmitt	ed during this print-out.		

< END OF ESTIMATES >