

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21002765/EVD3Q2
Date: 19/03/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00138382000
Claimant Vehicle No :	GBH158M	Insured Vehicle No :	SJD8316Y
Date of Loss:	12/10/2020	Nature of Claim:	TP
		Claim No:	SNM20D203856/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH158M		
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Engine No:	ZD30028818N
Reg. Date:	27/12/2017 (Man. Year: 2017)	Chassis No:	JN1SC2F24Z0860899
Colour:	Silver	Odometer:	99547 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15C	Rear Tyre Size:	195R15C
Front Left Side:	Yokohama 4 mm	Rear Left Side:	Yokohama 4 mm
Front Right Side:	Yokohama 4 mm	Rear Right Side:	Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,593.84	33.75	7,560.09	99.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,250.00	1,060.00	1,190.00	52.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,843.84	1,093.75	8,750.09	88.89
+ GST 7.00/7.00% (S\$)	689.07	76.56	612.51	88.89
Nett Amount (S\$)	10,532.91	1,170.31	9,362.60	88.89

INSPECTION

Date of Assignment:	16/03/2021	
Date Inspected:	02/03/2021	Inspected At:
		Efficient Motor & Engineering Works Pte Ltd (HQ) 56 Loyang Way #06-07, Loyang Enterprise Building Singapore 508775
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

3/19/2021

Adjuster Report

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 17 Mar 2021)	
Parts:	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH158M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH FRONT DOOR	Not Necessary	1,872.00 FL	*- FL
2	1		*LH FRONT TYRE INNER SHIELD REAR	Not Necessary	372.00 FL	*- FL
3	1		*LH SIDE GATE	Repair	2,600.60 FL	*- FL
4	1		*LH SIDE GATE LOWER BRACKET	Repair	34.70 FL	*- FL
5	5		*LH SIDE GATE HINGE	Not Necessary	940.50 FL	*- FL
6	1		*AIR CLEANER BOX	Not Necessary	1,005.60 FL	*- FL
7	2		*LH REAR TYRE FRONT & RR FENDER	Not Necessary	337.20 FL	*- FL
8	1		*LH SIDE GATE LOWER BRACKET RUBBER (2 Pcs)	Missing (1 Pc only)	75.00 FL	*37.50 FL
9	1		*BATTERY	Not Necessary	200.00 FS	*- FS
10	1		*LH SIDE GATE CHECKER PLATE	Not Necessary	750.00 FS	*- FS
11	1		*LH FRT DOOR CO.REG.STICKER	Not Necessary	30.00 FS	*- FS
12	1		*LH REAR TYRE	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,317.60	37.50
- List Item Discount on L Items 10.00/10.00% (S\$)	723.76	3.75
Total Parts (S\$)	7,593.84	33.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT & ALIGN LH SIDE PORTION,REMOVE & REPLACE DAMAGED PARTS	New	1,000.00	500.00
2	TO APPLY ANTI RUST COAT AND TUFF KOTE REPAIRED AREAS	New	100.00	30.00
3	TO CHECK AND RECTIFY LIGHTING & WIRING	New	50.00	30.00
4	TO REMOVE AND TRANSFER DOOR COMPONENTS	New	100.00	0.00
5	TO SPRAY PAINTING FOR LH SIDE GATE,FRT DR LH,FENDER LH FRT & RR PORTIONS & AFFECTED	New	1,000.00	500.00
Gross Labour Cost (\$\$)			2,250.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >