

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS21002769/UQD3E2

Date: 24/03/2021

REFERENCE

Insured/Claimant: SHARON ONG HWEE CHENG Policy No: MPC20A0005490
Date of Loss: 01/03/2021 Nature of Claim: OD Claim No: DMPC2100071H/NC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJN1515H**
Make & Model: LEXUS NX300, 2.0 E 5DR SUV (4WD) EXECUTIVE (A) Engine No: 8AR4217426
Reg. Date: 24/12/2019 (Man. Year: 2019) Chassis No: JTJBARBZ902228523
Colour: Grey Odometer: 23003 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$160,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R18 Rear Tyre Size: 225/60 R18
Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm
Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,188.50	2,727.00	3,461.50	55.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,840.00	1,690.00	1,150.00	40.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	9,028.50	4,417.00	4,611.50	51.08
+ GST 7.00/7.00% (\$\$)	632.00	309.19	322.81	51.08
Nett Amount (\$\$)	9,660.50	4,726.19	4,934.31	51.08

INSPECTION

Date of Assignment: 01/03/2021 Present Location: Falcon-Air Auto Services Pte Ltd (Tampines)
Date Inspected: 02/03/2021 Inspected At: Falcon-Air Auto Services Pte Ltd (Tampines)
Estimated Period of Repair: 5.0 days Blk 9006 #01-200 Tampines St 93
Singapore

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Mar 2021)

Parts: M1-SUV LEXUS NX300 2.0 E 5DR SUV (4WD) EXECUTIVE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJN1515H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*N/S FRONT DOOR LOWER GARNISH (WCP)	Grazed	180.00 F	*180.00 F
2	1		*N/S REAR DOOR (WCP)	Badly Dented	900.00 F	*900.00 F
3	1		*N/S REAR DOOR LOWER GARNISH (WCP)	Distorted	180.00 F	*180.00 F
4	1		*N/S REAR DOOR ARCH GARNISH (WCP)	Distorted	125.00 F	*125.00 F
5	1		*N/S REAR DOOR WEATHERSTRIP (WCP)	Not Necessary	150.00 F	*- F
6	1		*N/S REAR DOOR RUBBER (WCP)	Serviceable	90.00 F	*- F
7	1		*REAR BUMPER (WCP)	Cut	550.00 F	*550.00 F
8	1		*REAR BUMPER LOWER (WCP)	Not Necessary	300.00 F	*- F
9	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
10	1		*N/S REAR RIM (LOCAL REPAIR)	Cut	2,700.00 F	*400.00 FS
11	1		*N/S REAR FENDER ARCH GARNISH (WCP)	Serviceable	90.00 F	*- F
12	1		*N/S REAR BUMPER ARCH GARNISH (WCP)	Grazed	135.00 F	*135.00 F
13	1		*N/S REAR BUMPER SIDE RETAINER (WCP)	Not Necessary	50.00 F	*- F
14	1		*N/S REAR FENDER INNER SHIELD (WCP)	Not Necessary	85.00 F	*- F
15	1		*N/S REAR FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	5,635.00	2,520.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	553.50	207.00
Total Parts (\$\$)	6,188.50	2,727.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TRANSFER DOOR PARTS	New	120.00	60.00
3	COMPUTERISED WHEEL ALIGNMENT	New	120.00	60.00
4	TRANSFER TYRE TO NEW RIM AND BALANCING	New	50.00	0.00
5	TO DIAGNOSE AND RESET DOOR MEMORY }	New	250.00	80.00
6	INSTALL REVERSE SENSOR IN NEW BUMPER	New	80.00	40.00
7	TO RE-INITIALISE DOOR MEMORY AND REVERSE SENSOR }	New	250.00	0.00
8	LABOUR/PANEL BEATING	New	800.00	600.00
9	SPRAY PAINTING	New	1,000.00	750.00
10	TO REMOVE/REFIT TRIMS AND GARNISHES	New	120.00	80.00
Gross Labour Cost (\$)			2,840.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >