

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/190R GS1 Reg. No. 19-900/190-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	Re	ef:	CS/AGI21002785/Dtd3e2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate:	03/01/2022	
			Co	ode:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKW 6606L	Veh. Inspected		SHA 5934Y	
	Policy No.	P10448887R00	Coverage (\$)		0.00	
	Claim No.	C10009215/ST	Excess (\$)		0.00	
	Assign From	JULIE MANGUBAT	Assign Date		02/03/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI I40	c.c		1685	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	KMHLB41UMHU098300	Colour		BLUE	
	Odometer	635709 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	WEST LAKE		5 mm	
	L/H Front Tyre	205/60 R16	WEST LAKE		5 mm	
	R/H Rear Tyre	205/60 R16	WEST LAKE		5 mm	
	L/H Rear Tyre	205/60 R16	WEST LAKE		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	26/02/2021	Inspection Date		02/03/2021	
	Survey held at	BLK 9 SECTOR C# 01-42				
	Repairer	BIFROST AUTO PTE LTD				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

**8 Working Days** 

ESTIMATED NORMAL PERIOD FOR REPAIR: