

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21002791/ATD3N2**Date:** 15/12/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00094912000

**Claimant Vehicle No :** YP7404S **Insured Vehicle No :** GBG7237C

Date of Loss: 04/02/2021 Nature of Claim: TP Claim No: SNM21D201169/C02/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **YP7404S**

Make & Model: ISUZU NPR85, 3.0 D (M) Engine No: 4JJ12P6653

Reg. Date: 28/08/2017 (Man. Year: 2016) Chassis No: JAANPR85HG7100375

Colour: White Odometer: 183111 km

Engine Capacity: 2999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 7.00 R16 Rear Tyre Size: 7.00 R16

Front Left Side: Kenda 6 mm Rear Left Side: Kenda 6 mm

Front Right Side: Kenda 6 mm Rear Right Side: Kenda 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,128.00	1,700.00	1,428.00	45.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	900.00	400.00	500.00	55.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,028.00</b>	<b>2,100.00</b>	<b>1,928.00</b>	<b>47.86</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,700.00</b>		
<b>(S\$)</b>	4,028.00	1,700.00	2,328.00	57.80
<b>+ GST 7.00/7.00% (S\$)</b>	281.96	119.00	162.96	57.80
<b>Nett Amount (S\$)</b>	<b>4,309.96</b>	<b>1,819.00</b>	<b>2,490.96</b>	<b>57.80</b>

**INSPECTION**

Date of Assignment: 02/03/2021

Date Inspected: 10/03/2021 Inspected At: ComfortDelGro Engineering Pte Ltd (Ubi)  
320 UBI ROAD 3  
Singapore 408649

Estimated Period of Repair: 3.0 days

**Adjuster:** ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	(Last Synchronised: 15 Dec 2021)	
<b>Parts:</b>	N/A	ISUZU NPR85 3.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for YP7404S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		<b>*DOOR HINGES SS SIDE DOOR</b>	Not Necessary	320.00 FL	*- FL
2	1		<b>*DOOR HANDLE EXTERNAL ASSY WITH DOOR GEAR</b>	Not Necessary	960.00 FL	*- FL
3	1		<b>*SIDE DOOR WITH GASKET</b>	Torn	2,400.00 FL	*2,000.00 FL
F=Franchise part. L=ListItemDisc.						
				<b>Sub Total (\$\$)</b>	<b>3,680.00</b>	<b>2,000.00</b>
				<b>- List Item Discount on L Items 15.00/15.00% (\$\$)</b>	552.00	300.00
				<b>Total Parts (\$\$)</b>	<b>3,128.00</b>	<b>1,700.00</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	DISMANTLE DAMAGE SIDE DOOR & REPLACE NEW SIDE DOOR,RE-ALIGN,TIGHTEN & SECURE DOOR HINGES	New	900.00	400.00
<b>Gross Labour Cost (\$)</b>			<b>900.00</b>	<b>400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >