

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21002797/AGA3Q2
Date: 16/11/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SBH82Y	Insured Vehicle No :	SLU4468E
Date of Loss:	27/02/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000940

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBH82Y	Engine No:	CAV250075
Make & Model:	VOLKSWAGEN TOURAN, 1.4 TSI 1T32B4 (A)	Chassis No:	WVGZZZ1TZBW040982
Reg. Date:	24/01/2011 (Man. Year: 2010)	Odometer:	167602 km
Colour:	Black		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,437.75	8,144.89	16,292.86	66.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,560.00	1,750.00	1,810.00	50.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,997.75	9,894.89	18,102.86	64.66
Approved Total (Overridden) (S\$)		7,900.00		

(S\$)	27,997.75	7,900.00	20,097.75	71.78
+ GST 7.00/7.00% (S\$)	1,959.84	553.00	1,406.84	71.78
Nett Amount (S\$)	29,957.59	8,453.00	21,504.59	71.78
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,160.45		
Global Sum Settlement (S\$)		9,100.00		

INSPECTION

Date of Assignment: 02/03/2021

Date Inspected: 02/03/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Cas Garage Pte Ltd (HQ)
 No.1, Kaki Bukit Ave 6, #02-22 Autobay
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Sep 2021)
Parts:	M1-MPV	VOLKSWAGEN TOURAN 1.4 TSI 1T32B4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBH82Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	1,620.00 FL	*1,400.00 FL
2	2		*FRONT BONNET HINGES	Bent	283.00 FL	*283.00 FL
3	1		*FRONT BONNET LOCK	Not Necessary	197.00 FL	*- FL
4	1		*FRONT BONNET LATCH	Not Necessary	108.00 FL	*- FL
5	2		*BONNET SIDE RUBBER SEALS	Not Necessary	130.00 FL	*- FL
6	4		*BONNET STOPPERS	Not Necessary	46.80 FL	*- FL
7	1		*BONNET DAMPER	Not Necessary	133.00 FL	*- FL
8	1		*BONNET INSULATOR	Not Necessary	411.00 FL	*- FL
9	2		*BONNET WIPER NOZZLES	Not Necessary	170.00 FL	*- FL
10	1		*HEADLAMP RH	Cracked	775.50 FL	*775.50 FL
11	1		*HEADLAMP BRACKET RH	Cracked	84.90 FL	*84.90 FL
12	1		*HEADLAMP PANEL RH	Bent	95.70 FL	*95.70 FL
13	1		*FRONT BUMPER	Distorted	1,443.30 FL	*1,056.00 FL
14	1		*FRONT BUMPER RETAINERS	O/S Damaged	186.40 FL	*92.30 FL
15	1		*FRONT BUMPER GRILLE -TOP	Cracked	552.50 FL	*552.50 FL
16	1		*FRONT BUMPER -BOTTOM	Deformed	281.00 FL	*281.00 FL
17	1		*FRONT BUMPER LOGO	Necessary	145.00 FL	*145.00 FL
18	1		*FRONT BUMPER TOW COVER	Missing	78.70 FL	*78.70 FL
19	2		*FRONT FOG LAMP COVER	O/S Cracked / N/S Missing	276.60 FL	*138.30 FL
20	1		*FRONT BUMPER REINFORCEMENT UPPER	Bent	695.00 FL	*695.00 FL
21	1		*FRONT BUMPER REINFORCEMENT LOWER	Not Necessary	366.30 FL	*- FL
22	1		*FRONT BUMPER REINFORCEMENT SPONGE	Cracked	148.40 FL	*148.40 FL
23	1		*SUPPORT PANEL	Cracked	1,244.00 FL	*966.00 FL
24	1		*SUPPORT PANEL SIDE GARNISH	O/S Deformed	181.40 FL	*90.70 FL
25	1		*FRONT FENDER RH	Repair	801.50 FL	*- FL
26	1		*FRONT FENDER COWLING RH	Not Necessary	194.50 FL	*- FL
27	1		*RADIATOR ASSY	Dented	1,051.00 FL	*1,051.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*RADIATOR TOP HOSE W BOTTOM HOSE	Not Necessary	296.00 FL	*- FL
29	1		*RADIATOR BYPASS HOSE	Not Necessary	81.40 FL	*- FL
30	1		*RADIATOR FAN MOTOR -BIG	Not Necessary	943.00 FL	*- FL
31	1		*RADIATOR FAN MOTOR -SMALL	Not Necessary	634.00 FL	*- FL
32	1		*RADIATOR FAN COWLING	Cracked	202.00 FL	*202.00 FL
33	1		*AC CONDENSER	Dented	555.00 FL	*555.00 FL
34	1		*AC SUCTION HOSE	Not Necessary	845.00 FL	*- FL
35	1		*AC DISCHARGE HOSE	Not Necessary	638.50 FL	*- FL
36	1		*AC LIQUID PIPE	Not Necessary	504.50 FL	*- FL
37	1		*AC COMPRESSOR	Not Necessary	2,250.00 FL	*- FL
38	1		*INTAKE AIR DUCT -SUPPORT PANEL SIDE	Deformed	110.30 FL	*110.30 FL
39	1		*TURBO ASSY	Not Necessary	5,303.00 FL	*- FL
40	1		*TURBO AIR DUCT -TOP	Not Necessary	83.40 FL	*- FL
41	1		*TURBO AIR DUCT -BOTTOM	Not Necessary	120.80 FL	*- FL
42	1		*ALTERNATOR ASSY	Not Necessary	2,499.00 FL	*- FL
43	1		*WASHER TANK	Deformed	110.50 FL	*110.50 FL
44	2		*HORN	Damaged	120.60 FL	*60.30 FL
45	1		*SET BONNET INSULATOR CLIPS	Not Necessary	40.00 FS	*- FS
46	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
47	1		*SET FRONT FENDER COWLING CLIPS	Not Necessary	30.00 FS	*- FS
48	1		*BOTTLE COOLANT 4 LITRE	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	27,137.50	9,042.10
- List Item Discount on L Items 10.00/10.00% (\$)	2,699.75	897.21
Total Parts (\$)	24,437.75	8,144.89

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT/STRAIGHTEN /REALIGN ACCIDENT AFFECTED PORTION	New	1,800.00	1,000.00
2	TO RESPRAY ACCIDENT AFFECTED PORTION	New	1,200.00	600.00
3	TO CONDUCT WIRING CHECK AND REPAIR	New	120.00	30.00
4	TO REMOVE /REPLACE/REFIX RADIATOR PARTS INCLUDE REFILL COOLANT	New	180.00	60.00
5	TO REMOVE/REPLACE/REFIX AC PARTS ,VACUUM & REFILL AC GAS	New	180.00	60.00
6	TO ADJUST /FOCUS HEADLAMP	New	80.00	0.00
Gross Labour Cost (\$)			3,560.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >