

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21002798/R1EA3Q2**Date:** 17/06/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0002095_01

Claimant Vehicle No : SMR5421L **Insured Vehicle No :** SKX9490C

Date of Loss: 23/02/2021 Nature of Claim: TP Claim No: MFL2021D0000848

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMR5421L**
 Make & Model: MINI ONE, 1.5 5DR HB (LCI) (A) Engine No: H129K245B38A15A
 Reg. Date: 13/01/2020 (Man. Year: 2019) Chassis No: WMWXU520502L83383
 Colour: Blue Odometer: 26977 km
 Engine Capacity: 1499 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 RF16 Rear Tyre Size: 195/55 RF16
 Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
 Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,989.59	1,457.31	1,532.28	51.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,110.00	2,190.00	920.00	29.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,099.59	3,647.31	2,452.28	40.20
+ GST 7.00/7.00% (S\$)	426.97	255.31	171.66	40.20
Nett Amount (S\$)	6,526.56	3,902.62	2,623.94	40.20
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)		321.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,231.07		

INSPECTION

Date of Assignment: 02/03/2021

Date Inspected: 04/03/2021 Inspected At:

Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ)
27A Tanjong Penjuru
Singapore 609042

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Aug 2021)
Parts:	144	MINI ONE 1.5 5DR HB (LCI) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR5421L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	999.44 F	*999.44 F
2	1		*REAR BUMPER SPOILER	Scratched	290.29 F	*290.29 F
3	1		*PDC HOLDER LH	Necessary	60.39 F	*60.39 F
4	1		*PDC HOLDER RH	Necessary	60.39 F	*60.39 F
5	1		*COVER REAR FOGLIGHT	Serviceable	103.35 F	*- F
6	1		*REAR BUMPER REINFORCEMENT	Serviceable	571.61 F	*- F
7	2		*ULTRASONIC SENSOR	Serviceable	653.12 F	*- F
8	4		*SENSOR GASKET	Necessary	26.80 F	*26.80 F
9	1		*RR FOG LIGHT	Serviceable	174.20 F	*- F
10	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	2,989.59	1,457.31
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER ,BUMPER SPOILER .TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	1,260.00	840.00
2	TO RESPRAY REAR BUMPER	New	1,000.00	800.00
3	TO TRANSFER THE REVERSE SENSORS	New	250.00	150.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	250.00
Gross Labour Cost (\$\$)			3,110.00	2,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >