

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21002800/APA3Q2
Date: 16/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100377282	
Claimant Vehicle No :	SMX9809U	Insured Vehicle No :	SKN5187H	
Date of Loss:	27/02/2021	Nature of Claim:	TP	Claim No: 4990898472SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX9809U		
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Engine No:	L15B5576810
Reg. Date:	08/02/2021 (Man. Year: 2019)	Chassis No:	RU11326773
Colour:	Maroon	Odometer:	3289 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,650.80	305.60	1,345.20	81.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,390.00	550.00	840.00	60.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	3,040.80	855.60	2,185.20	71.86
	+ Loss of Use (3.0 x S\$60.00/day) (S\$)	180.00		
	+ Doc/Search Fee (S\$)	7.45		

Nett Liability (S\$)	1,043.05
Global Sum Settlement (S\$)	1,000.00

INSPECTION

Date of Assignment: 03/03/2021

Date Inspected: 03/03/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Premium Carz Services Pte Ltd (HQ)
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki
Singapore 417883

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Not Necessary	863.00 FL	*- FL
2	10		*REAR BUMPER CLIP	Not Necessary	55.00 FL	*- FL
3	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	32.00 FL	*- FL
4	1		*REAR BUMPER PAD RH	Deformed	212.00 FL	*212.00 FL
5	1		*REAR DOOR RH (NPA)	Not Necessary	0.00 FL	*- FL
6	1		*REAR FENDER RH (NPA)	Repair	0.00 FL	*- FL
7	1		*REAR FENDER ARCH RH	Cut	150.00 FL	*150.00 FL
8	8		*REAR FENDER ARCH CLIP	Necessary	44.00 FL	*20.00 FL
9	1		*REAR KNUCKLE ARM BEARING RH	Not Necessary	270.00 FL	*- FL
10	1		*REAR SPORT RIM RH	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,976.00	382.00
- List Item Discount on L Items 20.00/20.00% (\$)	325.20	76.40
Total Parts (\$)	1,650.80	305.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	40.00	30.00
2	PANEL BEATING CHARGES TO REMOVE AND REPLACE ,TO CUT AND WELD ,TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	600.00	200.00
3	SPRAY PAINTING ALL AFFECTED PARTS & AREAS	New	600.00	300.00
4	TO REMOVE AND REPLACE REAR KNUCKLE ARM BEARING RH & PRESS BEARING	New	120.00	0.00
5	TO SPRAY ANTI RUST PROOFING	New	30.00	20.00
Gross Labour Cost (\$\$)			1,390.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >