

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21002802/R1QD3E2

Date: 17/03/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700067464		
Claimant Vehicle No :	GBE7886P	Insured Vehicle No :	SFG1868Z		
Date of Loss:	23/02/2021	Nature of Claim:	TP	Claim No:	4673095787SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE7886P	Engine No:	1KD2588371
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFAT35Y20K206072
Reg. Date:	24/03/2016 (Man. Year: 2015)	Odometer:	176186 km
Colour:	Grey		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	155 R12C (D)
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 5/5 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	02/03/2021	Gold Autoworks Pte Ltd (HQ)
Date Inspected:	02/03/2021 Inspected At:	48 TOH GUAN ROAD EAST, #01-119
		ENTERPRISE HUB
		Singapore 608586
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	0.00 F	*- F
2	1		*REAR RUBBER STOPPER	Cut	0.00 F	*- F
3	1		*REAR RUBBER STOPPER BRACKET	Bent	0.00 F	*- F
4	1		*TAILGATE LOCK LH	Bent	0.00 F	*- F
5	1		*TAILGATE HINGE	Scratched	0.00 F	*- F
6	1		*REAR SIDEGATE	Repair	0.00 F	*- F
7	1		*REAR SIDEGATE LOCK	Bent	0.00 F	*- F
8	1		*REAR SIDEGATE HINGE	Scratched	0.00 F	*- F
9	1		*SIDEGATE LOWER PANEL	Bent	0.00 F	*- F
10	1		*STICKER	Necessary	0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >