

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG21002803/QBA3Q2

Date:

09/06/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No : SJE5831R

Date of Loss: 25/02/2021

Policy No:

Insured Vehicle No :

SMV3974A

Nature of Claim:

TP

Claim No:

7000527092SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJE5831R**

Make & Model: MITSUBISHI DELICA, 2.4 CVT (A)

Reg. Date: 30/04/2008 (Man. Year: 2007)

Colour: Beige

Engine Capacity: 2360 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 4B12AT9218

Chassis No: JMYLTCV5W7J000121

Odometer: 151338 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Handbrake (Serviceable):

Yes

Steering (Serviceable):

Engine Modification:

Yes

No

Footbrake (Serviceable):

Pre-accident Condition:

Yes

CONDITION OF TYRES

Front Tyre Size: 255/40Z R20

Front Left Side: AZENIS 6 mm

Front Right Side: AZENIS 6 mm

Rear Tyre Size:

Rear Left Side:

Rear Right Side:

255/40Z R20

AZENIS 6 mm

AZENIS 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,598.10	6,288.20	4,309.90	40.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,430.00	1,200.00	1,230.00	50.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,028.10	7,488.20	5,539.90	42.52
Approved Total (Overridden) (S\$)		6,000.00		

(S\$)	13,028.10	6,000.00	7,028.10	53.95
+ GST 7.00/7.00% (S\$)	911.97	420.00	491.97	53.95
Nett Amount (S\$)	13,940.07	6,420.00	7,520.07	53.95
+ Loss of Use (3.0 x S\$110.00/day) (S\$)		330.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		6,786.45		
Global Sum Settlement (S\$)		6,640.00		

INSPECTION

Date of Assignment: 02/03/2021

Date Inspected: 03/03/2021

Estimated Period of Repair: 3.0 days

Inspected At:

My Car Consultant Pte Ltd (Jalan Lam Huat) (HQ)
 60 Jalan Lam Huat, Carros Centre #05-21
 Singapore 737869

Adjuster: OI SUN PIN**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	1,875.00 FL	*1,875.00 FL
2	1		*BONNET LOCK	Serviceable	224.00 FL	*- FL
3	1		*FRONT BUMPER	Crumpled	1,599.00 FL	*1,480.00 FL
4	2		*FRONT BUMPER SIDE RETAINER	Broken (1 PCS ONLY)	118.00 FL	*58.00 FL
5	1		*FRONT BUMPER REINFORCEMENT	Serviceable	587.00 FL	*- FL
6	1		*FRONT BUMPER LOWER GRILLE CENTRE	Crumpled	498.00 FL	*384.00 FL
7	2		*FRONT BUMPER SENSOR	Serviceable	596.00 FL	*- FL
8	1		*FRONT BUMPER FOGLAMP RH	Cracked	321.00 FL	*220.00 FL
9	1		*FRONT BUMPER SIDE LIGHT RH	Scratched	158.00 FL	*158.00 FL
10	1		*FRONT RADIATOR GRILLE	Cracked	714.00 FL	*388.00 FL
11	1		*FRONT RADIATOR GRILLE LOGO	Necessary	58.00 FL	*58.00 FL
12	1		*HEADLAMP C/W BALLART RH	Crumpled	2,784.00 FL	*1,601.00 FL
13	1		*HEADLAMP LOWER BRACKET RH	Bent	159.00 FL	*159.00 FL
14	1		*FRONT FENDER RH	Repair	587.00 FL	*- FL
15	1		*FRONT FENDER COWLING RH	Cut	198.00 FL	*137.00 FL
16	1		*FRONT SUPPORT PANEL	Serviceable	612.00 FL	*- FL
17	1		*ENGINE UNDERCOVER	Cut	321.00 FL	*280.00 FL
18	1		*SET FRONT BUMPER PROTECTOR	Necessary	200.00 FS	*100.00 FS
19	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
20	1		*FRONT BUMPER LOWER COVER CLIPS	Necessary	50.00 FS	*20.00 FS
21	1		*FRONT FENDER INNER SHIELD CLIP	Necessary	30.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,739.00	6,968.00
- List Item Discount on L Items 10.00/10.00% (S\$)	1,140.90	679.80
Total Parts (S\$)	10,598.10	6,288.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ELECTRICAL WIRING	New	80.00	30.00
2	REFOCUS HEADLAMP BEAM	New	150.00	30.00
3	APPLY ANTI RUST ON AFFECTED AREAS	New	200.00	40.00
4	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	700.00
5	PANEL BEATING ON AFFECTED AREAS	New	1,000.00	400.00
Gross Labour Cost (S\$)			2,430.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >