



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4202S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	TO REPAIR SEE LABOUR	458.60	-
1	REAR BUMPER CENTER GUARD	DEFORMED	552.60	552.60
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	55.00	-
1	BOOTLID LAMP LH	NOT NECESSARY	233.90	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	TAILLAMP UPPER LH	CRACKED	557.90	557.90
	LESS 25% DISCOUNT		-470.00	-283.13
			1,410.00	849.37
<b>NETT ITEMS</b>				
1	REVERSE SENSOR (N)	NOT NECESSARY	135.70	-
	LESS 10% DISCOUNT		-13.57	-
			122.13	-
<b>LABOUR</b>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER.		400.00	350.00
	SPRAYPAINT CHARGE.		300.00	250.00
	R/I REVERSE SENSOR.		40.00	30.00
	R/I REVERSE SENSOR.	NOT NECESSARY	120.00	-
			860.00	630.00
<b>GRAND TOTAL</b>			<b>2,392.13</b>	<b>1,479.37</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>1,479.37</b>

Report Ref No. NS/INC21002811/T1tf3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.