

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21002813/DVD3E2
Date: 20/12/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 30001623288
Claimant Vehicle No : SHD6529L **Insured Vehicle No :** SMA706M
Date of Loss: 01/03/2021 Nature of Claim: TP Claim No: 254046

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD6529L**
Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2G04192
Reg. Date: 13/12/2019 (Man. Year: 2019) Chassis No: JTDKB3FU003090313
Colour: Blue Odometer: 137894 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm
Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,117.96	9,740.16	18,377.80	65.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,530.00	2,900.00	3,630.00	55.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	34,647.96	12,640.16	22,007.80	63.52
+ GST 7.00/7.00% (S\$)	2,425.36	884.81	1,540.55	63.52
Nett Amount (S\$)	37,073.32	13,524.97	23,548.35	63.52

INSPECTION

Date of Assignment: 02/03/2021
Date Inspected: 03/03/2021 Inspected At: Bifrost Auto Pte Ltd (sin Ming) (HQ)
Blk 9 Sector C, #01-42 Sin Ming Industrial Estate
Singapore 575644
Estimated Period of Repair: 8.0 days

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Nov 2021)

Parts: 144 TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD6529L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	642.04 FL	*642.04 FL
2	1		*REAR BUMPER SIDE RETAINER	Serviceable	157.78 FL	*- FL
3	1		*REAR BUMPER CLIPS	Necessary	30.80 FL	*30.80 FL
4	1		*REAR BUMPER SIDE CLIP	Not Necessary	35.00 FL	*- FL
5	1		*TAIL LAMP ASSY (UPPER) G5	Not Necessary	942.90 FL	*- FL
6	1		*TAIL LAMP ASSY (LOWER) G5	Not Necessary	860.58 FL	*- FL
7	1		*REAR FENDER LH	Dented	1,171.38 FL	*836.70 FL
8	1		*REAR FENDER SIDE PANEL (LH)	Not Necessary	231.00 FL	*- FL
9	1		*REAR FENDER SHIELD (LH)	Not Necessary	187.88 FL	*- FL
10	1		*REAR DOOR RUBBR SEAL OUTER	Not fitted	361.06 FL	*- FL
11	1		*PANEL SUB-ASSY, REAR DOOR, LH	Dented	1,761.62 FL	*1,294.90 FL
12	1		*REAR DOOR HINGE UPPER	Bent	115.22 FL	*115.22 FL
13	1		*REAR DOOR HINGE LOWER	Bent	115.22 FL	*115.22 FL
14	1		*REAR DOOR CHECK	Not Necessary	214.20 FL	*- FL
15	1		*REAR DOOR TRIMBOARD	Not Necessary	1,015.00 FL	*- FL
16	1		*MOTOR, POWER WINDOW REGULATOR FRT, LH	Not Necessary	1,318.52 FL	*- FL
17	1		*REGULATOR, FRONT DOOR, WINDOW REAR LH	Not Necessary	319.76 FL	*- FL
18	1		*DOOR CENTRE PILLAR	Dented	2,226.84 FL	*1,590.60 FL
19	1		*PANEL SUB-ASSY, FRONT DOOR, LH	Dented / Buckled	1,769.60 FL	*1,300.97 FL
20	1		*FRONT DOOR OUTER HANDLE (LH)	Not Necessary	530.46 FL	*- FL
21	1		*FRONT DOOR INNER LOCK	Not Necessary	964.32 FL	*- FL
22	1		*FRONT DOOR HINGE UPPER	Not Necessary	115.22 FL	*- FL
23	1		*FRONT DOOR HINGE LOWER	Not Necessary	127.68 FL	*- FL
24	1		*FRONT DOOR CHECK	Not Necessary	214.93 FL	*- FL
25	1		*FRONT DOOR TRIMBOARD	Not Necessary	1,015.00 FL	*- FL
26	1		*FRONT DOOR OUTER MOULDING	Serviceable	264.04 FL	*- FL
27	1		*FRONT DOOR WEATHER STRIP	Not Necessary	641.06 FL	*- FL
28	1		*FRONT DOOR RUBBER SEAL	Not Necessary	359.80 FL	*- FL
29	1		*MOTOR ASSY, POWER WINDOW FRT, LH	Not Necessary	1,318.52 FL	*- FL
30	1		*REGULATOR, FRONT DOOR WINDOW FRT, LH	Not Necessary	319.76 FL	*- FL
31	1		*MIRROR ASSY, OUTER REAR VIEW, LH	Broken	2,420.18 FL	*1,374.20 FL
32	1		*KEY LOCK, ANTENNA	Not Necessary	436.80 FL	*- FL
33	1		*FRONT DOOR COMFORT LOGO	Necessary	105.00 FN	*105.00 F
34	1		*CENTRE ROCKER PANEL (GARNISH)	Distorted / Dented	806.40 FL	*576.00 FL
35	1		*REAR TYRE (LH)	Serviceable	302.40 FL	*- FL
36	1		*REAR TYRE RIM (LH)	Distorted / Bent	2,177.00 FL	*1,570.55 FL
37	1		*REAR WHEEL HUB CAP (LH)	Bent	248.78 FL	*177.10 FL
38	1		*REAR WHEEL BEARING ING & HUB	Damaged	854.28 FL	*493.00 FL
39	1		*REAR CROSS MEMBER	Not Necessary	3,080.56 FL	*- FL
40	1		*REAR SHOCK ABSORBER	Distorted	165.62 FL	*165.62 FL
41	1		*REAR SHOCK ABSORBER MOUNTING	Not Necessary	175.42 FL	*- FL
42	1		*REAR LOWER ARM	Distorted	696.50 FL	*497.50 FL
43	1		*REAR UPPER ARM	Distorted	499.52 FL	*356.80 FL
44	1		*REAR KNUCKLE ARM	Distorted	1,134.84 FL	*810.60 FL
45	1		*REAR COIL SPRING	Not Necessary	267.96 FL	*- FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*REAR COIL SPRING MOUNTING (NPA)	Not Necessary	0.00 FL	*- FL
47	1		*REAR BRAKE ABS SENSOR (WIRE)	Not Necessary	110.32 FL	*- FL
48	1		*REAR STABILIZER BAR	Not Necessary	436.10 FL	*- FL
49	1		*REAR STABILIZER LINK	Not Necessary	212.24 FL	*- FL
50	1		*REAR TRAILING ARM	Distorted	439.88 FL	*314.20 FL
51	1		*REAR ASSIST ARM	Distorted	479.08 FL	*342.20 FL
52	1		*FRONT FENDER HYBRID EMBLEM LH	Not Necessary	121.10 FL	*- FL
53	1		*REAR BUMPER RUBBER MAT	Necessary	70.00 FS	*70.00 FS
54	1		*REAR DOOR COMFORT & APPS STICKER	Necessary	112.00 FS	*112.00 FS
55	1		*FRONT DOOR HANDLE BASE	Not Necessary	402.78 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$)	35,101.95	12,891.22
- List Item Discount on L Items 20.00/25.00% (\$)	6,962.99	3,151.06
- Nett Item Discount on N Items 20.00/0.00% (\$)	21.00	0.00
Total Parts (\$)	28,117.96	9,740.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	1,200.00
2	SPRAY PAINTING CHARGE	New	1,800.00	1,000.00
3	WIRING CHARGE	New	120.00	30.00
4	TUFF KOTE	New	150.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE / REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE / REFIX REAR WINDSCREEN GLASS	New	120.00	0.00
8	REMOVE / REFIX REVERSE SENSOR	New	120.00	40.00
9	REMOVE / REFIX UNDERCARRIAGE (RR)	New	400.00	150.00
10	RE-SET REAR ABS SYSTEM	New	400.00	0.00
11	REMOVE / REFIX FUEL TANK	New	80.00	0.00
12	REMOVE / REFIX EXHAUST PIPE	New	80.00	0.00
13	TRANSFER OF DOOR MECHANISM FRONT	New	80.00	60.00
14	RE-SET FRT POWER WINDOW SYSTEM	New	200.00	0.00
15	TRANSFER OF DOOR MECHANISM REAR	New	80.00	60.00
16	RE-SET REAR POWER WINDOW SYSTEM	New	200.00	0.00
17	FOUR WHEEL ALIGNMENT	New	120.00	60.00
18	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	180.00
			Gross Labour Cost (\$\$)	6,530.00
				2,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >