



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBK 8033X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
4	FLOOR PANEL LH HOOK @\$137.60 (CONSISTENT)	NOT NECESSARY	550.40	-
1	FLOOR PANEL LH MOULDING (CONSISTENT)	NOT NECESSARY	190.20	-
1	LH SIDE GATE (CONSISTENT)	TO REPAIR SEE LABOUR	1,409.00	-
4	LH SIDE GATE HINGES @\$66.30(CONSISTENT)	DENTED (2 PCS ONLY)	265.20	132.60
1	REAR LH FENDER (FRONT)(CONSISTENT)	DENTED	306.75	306.75
1	REAR LH FENDER (REAR)(CONSISTENT)	DENTED	297.95	297.95
1	REAR LH FLIP LOCK HANDLE (CONSISTENT)	NOT NECESSARY	115.90	-
1	REAR LH MUDFLAP (CONSISTENT)	NOT NECESSARY	230.10	-
1	REAR LH STOPPER (CONSISTENT)	MISSING	43.10	43.10
1	REAR LH STOPPER BRACKET (CONSISTENT)	TO REPAIR SEE LABOUR	98.60	-
1	REAR LH WHEEL RIM (CONSISTENT)	CUT	224.70	224.70
	LESS 25% DISCOUNT		-932.98	-251.28
			2,798.92	753.82
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR LH TYRE (SN)(CONSISTENT)	CUT	200.00	180.00
			200.00	180.00
<b><u>LABOUR</u></b>				
	TO ROAD TEST DRIVING ,CHECK AND RESETTNG WHEEL ALIGNMENT SYSTEM.		80.00	80.00
	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT.		800.00	550.00
	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENT AND DAMAGED CONSISTENT TO THE ACCIDENT .INCLUSIVE OF THE REPAIR OF LH SIDE GATE AND REAR LH STOPPER BRACKET .		1,000.00	300.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		80.00	30.00
			1,960.00	960.00
GRAND TOTAL			4,958.92	1,893.82
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,500.00

Report Ref No. CC4/ASM21002814/Ags3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.