

ESTIMATE

Company Reg No. 200609327M
 GST Reg No. MP-8500111-X

Invoice Name & Address				Owner Name & Vehicle Info		
Fan Wan Ping Julie				/Fan Wan Ping Julie		
Blk 426 Jurong West Ave 1				Reg No/Reg Date	SLU7473U	/ 13/12/2017
#07-332				Date In/Mileage	/	0
Singapore 640426				Chassis No	VF73ABHZTHJ772777	
Contact No Mobile: 97299665				Engine No	10JBHD3087244	
				Make/Model	CIT/GC4P 1.6 BLUEHDI EAT6 INTENSIVE ML	
				Colour/Trim	F4M GRIS ARTENSE / IXF YATAGO GREY	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	01/03/2021/ 17:51	QUD	247 / DonBong	16252

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER FACE, REPAIR REAR END PANEL	760 X1			2280.00
E PNT88000 REMOVE AND INSTALL PARKING ASSIST				120.00 /
E PNT98000 PAINT WORK SPRAY REAR END PANEL, REAR BUMPER AND AFFECTED PORTION	550 X2			1650.00
M SUNDRY PERFORM RUST PREVENTION				80.00 X
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				50.00 /
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				380.00 /
M SUNDRY SUNDRIES				20 50.00
M REAR BUMPER	1.00	1120.00	0.00	1120.00
M BUMPER BRACKET	1.00	338.00	0.00	338.00
M BUMPER SKIRT	1.00	370.00	0.00	370.00
M RECESS DOOR	1.00	72.00	0.00	72.00
M BRACKET SET	1.00	138.00	0.00	138.00
M BRACKET SET LAT	1.00	138.00	0.00	138.00
M BUMPER SEAL	1.00	52.00	0.00	52.00
M BUMPER BRACKET	1.00	334.00	0.00	334.00
M ANGLEPLATE	1.00	56.00	0.00	56.00
M STIFFENER LH	1.00	100.00	0.00	100.00
M STIFFENER RH	1.00	100.00	0.00	100.00
M BUMPER BRACKET	1.00	90.00	0.00	90.00
M LOW RR PAN FIX	1.00	168.00	0.00	168.00
M SENSOR SUPPORT	1.00	160.00	0.00	160.00
M SENSOR	2.00	191.00	0.00	382.00
M SENSOR	2.00	270.00	0.00	540.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

Company Reg No. 200609327M
GST Reg No. MR-8500111-X

Invoice Name & Address				Owner Name & Vehicle Info							
Fan Wan Ping Julie				Cust No/Name / Fan Wan Ping Julie							
Blk 426 Jurong West Ave 1				Reg No/Reg Date SLU7473U / 13/12/2017							
#07-332				Date In/Mileage / 0							
Singapore 640426				Chassis No VF73ABHZTHJ772777							
				Engine No 10JBHD3087244							
Contact No Mobile: 97299665				Make/Model CIT/GC4P 1.6 BLUEHDI EAT6 INTENSIVE ML							
				Colour/Trim F4M GRIS ARTESE / IXF YATAGO GREY							
Account No				Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00073				Cash	01/03/2021/ 17:51	QUD	247 / DonBong	16252			
Description of Goods / Services								Qty	Unit Price	Disc%	Amount
M SENSOR SUPPORT								4.00	160.00	0.00	640.00

Estimate

SURVEYOR NAME: Steve CLKK) wil An

SURVEYOR SIGNATURE: 23/3/21, 12.27p

DATE: P/P

REMARKS: 4 days

LXZ Auto Components hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Confirm & accepted by Ins prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Authorized signatory and company stamp

Parts	4,798.00
Labour	4,480.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	130.00
Total(w/o GST)	9,408.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.