



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving TPVD UNKNOWN UNKNOWN (GBK4282U)

Date of Loss 1 March 2021

Time of Loss 13.40

Loss Description XD2226Y (INSD) C/W GBK4282U (TP)

Comment

Workshop Details

Total Rebate Amount 23448

Nett Loss Amount \$60,552.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (TP)

Days of work completion * 20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#	GBK4282U	Purchase Date	<div>dd/mm/yyyy</div> <div></div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>27/07/2020</div> <div></div>
Mileage	<div>17205</div>	Age of Vehicle	0

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<div>2018</div>
Make	TPVD UNKNOWN	<div>SSANGYONG</div>

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	TBC	<div></div>
Date of Birth	1 January 1999	<div>dd/mm/yyyy</div> <div></div>

Model CATEGORY	UNKNOWN POLICY INFORMATION	ACTYON SPORTS 2.2D
Type		<div>▼</div>
Type of Paint		
Chassis No		KPADA1EESJP329646
Engine No		67296022616484
Engine Capacity		2157
Sum Insured		0
Market Value		84000

CATEGORY Age	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	<div>▼</div>
Driving Experience	0	
Driver License #		
License Type		<div>▼</div>
License Issue Date		<div>dd/mm/yyyy</div> <div></div>
License Expiration Date		<div>dd/mm/yyyy</div> <div></div>

CATEGORY	FNOL INFORMATION	POST SURVEY
Address	SG, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="▼"/>
Gender	Unknown	<input type="text" value="▼"/>
Marital status	Unknown	<input type="text" value="▼"/>
Identification #	TBC	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

08/03/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver
Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text" value="10"/>	Settlement%	<input type="text" value="100"/>

Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

YesNo

Part Supplied by AXA

YesNo

Save



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts














Add







Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR TAIL GATE	Bent	0	1950	No		10			1755	Reviewing
<input type="checkbox"/>		0	1		REAR TAIL GATE LOCK RH	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR TAIL GATE LOCK LH	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR TAIL GATE HINGE LH	Damaged	0	165	No		10			148.5	Reviewing
<input type="checkbox"/>		0	1		REAR TAIL GATE HINGE RH	Damaged	0	165	No		10			148.5	Reviewing
<input type="checkbox"/>		0	1		REAR TAIL GATE EMBLEM SSANGYONG	Necessary	0	65	No		10			58.5	Reviewing
<input type="checkbox"/>		0	1		REAR TAIL GATE EMBLEM ACTYON SPORTS	Necessary	0	65	No		10			58.5	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR TAIL GATE LOGO	Necessary	0	95	No		10			85.5	Reviewing
<input type="checkbox"/>		0	1		REAR TAIL GATE INNER TRIM	Damaged	0	350	No		10			315	Reviewing
<input type="checkbox"/>		0	1		REAR END PANEL	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR DOOR LH	Bent	0	1410	No		10			1269	Reviewing
<input type="checkbox"/>		0	1		REAR FENDER LH	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR BUMPER	Buckled	0	220	No		10			198	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER REFLECTOR LH	Damaged	0	230	No		10			207	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER REFLECTOR RH	Damaged	0	230	No		10			207	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER BRACKET LH	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR BUMPER BRACKET RH	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR BUMPER REINFORCEMENT	Bent	0	110	No		10			99	Reviewing
<input type="checkbox"/>		0	1		REAR NO. PLATE LAMP LH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR NO. PLATE LAMP RH	Serviceable	0	0	No		10			0	Deny

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		TAIL LAMP LH	Cracked	0	515	No		10			463.5	Reviewing
<input type="checkbox"/>		0	1		TAIL LAMP RH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR OUTER HANDLE	Cracked	0	290	No		10			261	Reviewing
<input type="checkbox"/>		0	1		REAR TAIL GATE CABLE RH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR TAIL GATE CABLE LH	Dented	0	190	No		10			171	Reviewing
<input type="checkbox"/>		0	1		REAR CABIN GARNISH (PLASTIC)	Serviceable	0	0	No		10			0	Deny






Labour



Add

Approve

Deny

Submit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		STRAIGHTEN & PANEL BEAT ON ACCIDENT AREA	0	600	0	0	Reviewing	
<input type="checkbox"/>		0		SPRAY PAINT ON ACCIDENT AREA	0	800	0	0	Reviewing	
<input type="checkbox"/>		0		CHECK & REPAIR WIRING SYSTEM	0	20	0	0	Reviewing	
<input type="checkbox"/>		0		R&R TAILGATE SYSTEM	0	50	0	0	Reviewing	
<input type="checkbox"/>		0		R&R CABIN TO ASSIST REPAIR	0	0	0	0	Deny	

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		RESPRAY TUFF KOTE ON AFFECTED AREA	0	60	0	0	Reviewing	
<input type="checkbox"/>		0		CONDUCT CHASSIS ALIGNMENT	0	0	0	0	Deny	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary












Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	DAYS OF REPAIR : 5 DAYS	Reviewing		0		
<input type="checkbox"/>		0	1 SET REAR BUMPER CLIPS	Reviewing		50	NECESSARY	
<input type="checkbox"/>		0	1 SET REAR BUMPER PROTECTOR	Deny		0	NOT NECESSARY	
<input type="checkbox"/>		-	REAR	-	-	-	-	

	 EDIT	0 SR NO	NUMBER NAME	Deny ACTION	ESTIMATED AMOUNT	0 ADJUSTED AMOUNT	SERVICEABLE COMMENT	 REMOVE
<input type="checkbox"/>		0	REAR END PANEL SEALANT	Deny		0	NOT NECESSARY	
<input type="checkbox"/>		0	REAR TAIL GATE STICKER 70KM	Reviewing		12	NECESSARY	
<input type="checkbox"/>		0	REAR FENDER INNER TRIMBOARD CLIPS	Deny		0	NOT NECESSARY	
<input type="checkbox"/>		0	1 SET REAR CABIN GARNISH CLIPS	Deny		0	NOT NECESSARY	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount

\$0.00

Adjusted Claim Amount

\$7,037.00

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts	\$0.00	\$5,445.00
Labour	\$0.00	\$1,530.00
Miscellaneous	\$0.00	\$62.00


Submit for Review

<<

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

- Add
- Approve
- Deny
- Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>	0	FINAL LUMP SUM	Reviewing		5600		

Submit for Review