

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE I	PTE LTD		Ref:	CS3/ASM21002823/T1qd3e2	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11		Date:	09/03/2021	
	ATTN: TAN JUNHO	ONG		Code:	ASM	
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHC 8526L	Veh. Inspected		GBB 7906G	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S1M033Z4	Excess (\$)		0.00	
	Assign From	TAN JUNHONG	Assign Date		02/03/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA HIACE 3.0	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2008	
	Chassis No.	KDH2010014181	Colour		SILVER	
	Odometer	229837 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195 R15	HABILEAD		6 mm	
	L/H Front Tyre	195 R15	HABILEAD		6 mm	
	R/H Rear Tyre	195 R15	HABILEAD		6 mm	
	L/H Rear Tyre	195 R15	HABILEAD		6 mm	
4. Description of Damages						
	THE VEHICLE SUS	/EHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5.	General Information					
	Accident Date	25/02/2021	Inspect Date /	Time	04/03/2021 (02:18 PM)	
	Survey held at	TOPMAX AUTO BODYSHOP				
		BLK 3007 UBI ROAD 1 #01-410 . SINGAPORE 408701				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000					
5b.	5b. Estimate Days of Repair					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000					
SUIT ATTENDED TO DE DE DE DATE DE LA COMPANIO DE LA COMPANIO DE DATE DE LA COMPANIO DEL COMPANIO DE LA COMPANIO DE LA COMPANIO DEL COMPANIO DE LA COMPANIO DEL COMPANIO						

Report Ref No. CS3/ASM21002823/T1qd3e2

Inspected By

MOHAMAD TAUFIKH

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

6 Working Days

M.MATAI, AMSAE-A $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ **Automotive Assessor**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.