



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 829R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER-RR BUMPER	CRACKED	459.40	459.40
1	MOULDING ASSY-RR BUMPER C	CUT	451.25	451.25
1	MOULDING ASSY-SIDE SILL R	TO REPAIR SEE LABOUR	290.00	-
1	LAMP ASSY-REAR COMB OUTSI	CUT	870.40	870.40
1	PANEL ASSY-QUARTER OUTER	TO REPAIR SEE LABOUR	1,768.30	-
1	REFLECTOR/REFLEX ASSY-RR	CUT	41.45	41.45
10	BUMPER COVER CLIP REAR	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-780.56	-368.90
			3,122.24	1,475.60
LABOUR				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF MOULDING ASSY-SIDE SILL R AND PANEL ASSY-QUARTER OUTER.		1,100.00	875.00
	SPRAYPAINT CHARGE.		1,000.00	750.00
	CHECK ALL LIGHTING.		20.00	20.00
	TUFF COAT ON AFFECTED PARTS.	NOT NECESSARY	30.00	-
			2,150.00	1,645.00
GRAND TOTAL			5,272.24	3,120.60
RECOMMENDED COST OF REPAIRS (CONFIRMED)				3,120.60

Report Ref No. NS/INC21002832/T1vd3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.