

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21002834/GGS3Q2
Date: 29/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993623
Claimant Vehicle No :	SLR4663Z	Insured Vehicle No :	SMY794G
Date of Loss:	26/02/2021	Nature of Claim:	TP
		Claim No:	5507869304SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR4663Z	Engine No:	2ZR1978906
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	ZVW400025848
Reg. Date:	16/08/2017 (Man. Year: 2017)	Odometer:	334611 km
Colour:	Grey		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,229.30	1,651.67	2,577.63	60.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	1,100.00	250.00	18.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,579.30	2,751.67	2,827.63	50.68
Approved Total (Overridden) (S\$)		2,200.00		

(S\$)	5,579.30	2,200.00	3,379.30	60.57
+ GST 7.00/7.00% (S\$)	390.55	154.00	236.55	60.57
Nett Amount (S\$)	5,969.85	2,354.00	3,615.85	60.57
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,761.45		

INSPECTION

Date of Assignment: 03/03/2021

Date Inspected: 03/03/2021

Estimated Period of Repair: 4.0 days

Inspected At: Allswell Motor Traders (HQ)
25 Defu Lane 9
Singapore 539266

Adjuster: XING GUO QIANG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*END PANEL	Repair	795.00 F	*- FL
2	1		*TAILGATE	Buckled	980.00 F	*980.00 FL
3	1		*REAR BUMPER	Deformed	1,315.00 F	*602.56 FL
4	1		*LH RETAINER	Not Necessary	55.00 F	*- FL
5	1		*RH RETAINER	Deformed	55.00 F	*55.00 FL
6	1		*END PANEL TOP GARNISH	Not Necessary	179.00 F	*- FL
7	1		*KEYLESS SENSOR	Not Necessary	240.00 F	*- FL
8	2		*WINDSCREEN MOULDING	Necessary	185.00 F	*140.00 FL
9	1		*TAILGATE RUBBER	Necessary	218.00 F	*218.00 FL
10	1		*WINDSCREEN SEALANT	Necessary	60.00 FS	*50.00 FS
11	1		*CLIPS/RETAINER STUDS FOR BUMPER TAILGATE BACK GARNISH ,END PANEL TOP GARNISH & ETC	Necessary	45.00 FS	*30.00 FS
12	1		*TAILGATE PRIUS EMBLEM	Scratched	52.30 F	*50.00 FL
13	1		*TAILGATE EMBLEM	Scratched	50.00 F	*50.00 FL
					Sub Total (\$\$)	4,229.30 2,175.56
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00 523.89
					Total Parts (\$\$)	4,229.30 1,651.67

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE/REFIX WINDSCREEN REAR	New	150.00	100.00
2	DISMANTLE /ASSEMBLY OF ALL AFFECTED PARTS	New	400.00	400.00
3	SPRAY PAINT TAILGATE X2 ,BUMPER FENDER X2	New	800.00	600.00
Gross Labour Cost (\$\$)			1,350.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >