

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19005856/NGA3Q2-1
Date: 20/04/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015		
Claimant				
Vehicle No : GY9392U	Insured Vehicle No :	SHA4974M		
Date of Loss: 29/03/2019	Nature of Claim:	TP	Claim No:	MCT19030824

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GY9392U		
Make & Model:	HYUNDAI HRLowDECK, 2.5 D (M)	Engine No:	D4BH4071706
Reg. Date:	29/09/2005 (Man. Year: 2004)	Chassis No:	KMFZCN7HR5U077805
Colour:	White	Odometer:	317081 km
Engine Capacity:	2476 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	155 R12C (D)
Front Left Side:	West Lake 6 mm	Rear Left Side:	Hankook 6/6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	Hankook 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,193.55	1,557.08	1,636.47	51.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,620.00	970.00	650.00	40.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,813.55	2,527.08	2,286.47	47.50
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	4,813.55	2,000.00	2,813.55	58.45
+ GST 7.00/7.00% (S\$)	336.95	140.00	196.95	58.45
Nett Amount (S\$)	5,150.50	2,140.00	3,010.50	58.45
+ Car Rental (6.0 x S\$100.00/day + 7.00% GST) (S\$)		642.00		
(S\$)		2,782.00		
Liabile Amount (50.00%) (S\$)		1,391.00		

INSPECTION

Date of Assignment:	02/04/2019		
Date Inspected:	22/05/2019	Inspected At:	Hua Hong Pte Ltd (Sungei Kadut) 25D Sungei Kadut Street 1 Singapore 729332
Estimated Period of Repair:	3.0 days		

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Apr 2021)	
Parts:	N/A	HYUNDAI HRLOWDECK 2.5 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GY9392U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	512.10 FL	*512.10 FL
2	2		*FRONT BUMPER RETAINER (LH/RH)	Cracked	76.00 FL	*76.00 FL
3	10		*FRONT BUMPER CLIP	Necessary	30.00 FL	*30.00 FL
4	1		*FRONT GRILLE	Deformed	43.50 FL	*43.50 FL
5	1		*EMBLEM	Necessary	40.80 FL	*40.80 FL
6	1		*FRONT PANEL	Repair	1,341.10 FL	*- FL
7	1		*FRONT HEAD LAMP (LH)	Scratched	373.80 FL	*373.80 FL
8	1		*FRONT CORNER PANEL (LH)	Repair	109.10 FL	*- FL
9	1		*FRONT OIL COOLER	Deformed	495.00 FL	*495.00 FL
10	1		*FRONT REINFORCEMENT	Serviceable	303.10 FL	*- FL
11	1		*FRONT REINFORCEMENT BRACKET (LH/RH)	Deformed	130.00 FL	*65.00 FL
12	0		*FRONT NUMBER PALTE REPEATED		-	-
13	1		*WASHER TANK MOTOR	Broken	55.00 FL	*55.00 FL
14	1		*FRONT NUMBER PLATE	Cracked	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,544.50	1,726.20
- List Item Discount on L Items 10.00/10.00% (\$\$)	350.95	169.12
Total Parts (\$\$)	3,193.55	1,557.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE ,CUT & WELD FRONT PANEL ,FRONT BUMPER ,FRONT GRILLE ,FRONT LH HEAD LAMP ,FRONT REINFORCEMENT ,KNOCKING & PULL STRAIGHT FRONT CHASSIS FRAME AND ALL AREA AFFECTED BY ACCIDENT	New	800.00	450.00
2	TO PERFORM WIRE CHECKING	New	20.00	20.00
3	TO SPRAY FRONT PANEL ,FRONT GRILLE ,FRONT BUMPER AND FRONT REINFORCEMENT	New	800.00	500.00
			Gross Labour Cost (\$)	1,620.00
				970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >