

Lt R8

COMFORTDELGRO ENGINEERING PTE LTD

Date: 01.03.2021

REPAIR ESTIMATE

China Taiping (LTS)
LKK-

Time: 13:22:03

Page: 1/3

IS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305456320
REGN NO : SHD3054J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 14.07.2016
DATE/TIME IN : 01.03.2021 09:25
ACCIDENT DATE : 28.02.2021

JOB / PARTS DESCRIPTION QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT	Notes
0001 04-01-0103-0579-G REAR BUMPER	1		1,106.00	20.00	884.80	- BR
0002 04-01-0103-0783-G REAR BUMPER SIDE BRKT RH	1		35.60	20.00	28.48	?
0003 04-01-0101-0111-G REAR BUMPER CLIPS	10	L	22.00	20.00	17.60	- MC
0004 04-01-0103-0585-A TAILLAMP RH	1		697.80	20.00	558.24	- CPA
0005 04-01-0103-0658-G REAR WHEEL CAP RH	1		217.20	20.00	173.76	- CA
0006 04-01-0103-0575-G REAR FENDER RH	1		2,171.40	20.00	1,737.12	X Base Repair
0007 03-01-0103-0122-G REAR FENDER SHIELD RH	1		169.30	20.00	135.44	- CA
0008 04-01-0103-0595-G REAR DOOR RH	1		2,201.10	20.00	1,760.88	X Repair
0009 04-01-0103-0745-G REAR WINDSCREEN MOULDING	1		51.80	20.00	41.44	X MC NN
0010 04-01-0103-1150-A REAR BUMPER MAT	1		50.00		50.00	- MC
0011 28-01-9999-2023-A REAR DOOR APPS STICKER RH	1		80.00		80.00	- MC
0012 05-01-0199-0032-A WINDSCREEN AHESIVE-310ML	2		92.00		92.00	X MC NN
					SUB-TOTAL	: 5,559.76

JOB NATURE

€
Jo
Ser
urne

COMFORTDELGRO ENGINEERING PTE LTD

Date: 01.03.2021

Time: 13:22:03

Page: 2

REPAIR ESTIMATE

China Taiping (L/S)

LKP

JOB NO : 305456320
 REGN NO : SHD3054J
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 14.07.2016
 DATE TIME IN : 01.03.2021 09:25
 ACCIDENT DATE : 28.02.2021

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0000 PB PANEL BEATING	900.00		560		
0001 SP SPRAYPAINT CHARGE	900.00		750		
0002 17-01 CHECK ALL LIGHTING	40.00		30		
0003 20-00 TUFF COAT ON AFFECTED PARTS.	60.00		X NN		
0004 L R/I REVERSE SENSOR	120.00		40		
0005 L R/I UPHOPSTERY ETC	150.00		60		
0006 L R/I REAR WINDSCREEN	150.00		X NN		
0007 L WHEEL ALIGNMENT	120.00		60		
SUB-TOTAL :					2,440.00

4 Days

L/S

After repair photos.

Gene Qs up

01/3/21

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING PTE LTD

Date: 01.03.2021

Time: 13:22:03

REPAIR ESTIMATE

China Taiping (LTS)

Page: 3

B TS

LKK-

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305456320
REGN NO : SHD3054J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 14.07.2016
DATE/TIME IN : 01.03.2021 09:25
ACCIDENT DATE : 28.02.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 7,999.76

Lmfs

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :