

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21002850/KQD3E2

Date: 15/03/2021

REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD. Policy No: 0999993662

Date of Loss: 17/02/2021

Nature of Claim: OD

Claim No: 8596853991SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMQ2435Y**
Make & Model: MERCEDES-BENZ GLA180, 1.6 (A) Engine No: 27091031914487
Reg. Date: 04/11/2019 (Man. Year: 2019) Chassis No: WDC1569422J663008
Colour: Metallic Red Odometer: 19348 km
Engine Capacity: 1595 cc
Market Value/New Car Price: S\$126,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50R18 Rear Tyre Size: 235/50R18
Front Left Side: Continental 9 mm Rear Left Side: Continental 9 mm
Front Right Side: Continental 9 mm Rear Right Side: Continental 9 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 3,751.00 | 2,492.60 | 1,258.40 | 33.55 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,130.00 | 680.00 | 1,450.00 | 68.08 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 5,881.00 | 3,172.60 | 2,708.40 | 46.05 |
| + GST 7.00/7.00% (S\$) | 411.67 | 222.08 | 189.59 | 46.05 |
| Nett Amount (S\$) | 6,292.67 | 3,394.68 | 2,897.99 | 46.05 |

INSPECTION

Date of Assignment: 03/03/2021

Date Inspected: 03/03/2021 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,414.80 NETT)

EXCESS : \$5,200.00

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|-----------------------|------------|-------------|
| 1 | 1 | | *HEADLAMP ASSY-RH (WCP) | Cut | 1,480.00 F | *1,480.00 F |
| 2 | 1 | | *FRONT BUMPER (WCP) | *Check | 850.00 F | *- F |
| 3 | 1 | | *FRONT BUMPER SIDE RETAINER-RH (WCP) | Serviceable | 38.00 F | *- F |
| 4 | 1 | | *FRONT BUMPER SENSOR (WCP) | Scratched (1 Pc only) | 276.00 F | *138.00 F |
| 5 | 6 | | *FRONT BUMPER SENSOR SEALS (WCP) | *Check | 48.00 F | *- F |
| 6 | 1 | | *FRONT BUMPER FOG LAMP COVER-RH (WCP) | Missing | 68.00 F | *68.00 F |
| 7 | 1 | | *FRONT BUMPER FOG LAMP COVER BASE-RH (WCP) | *Check | 70.00 F | *- F |
| 8 | 1 | | *FRONT BUMPER LOWER GRILLE OUTER CHROME (WCP) | Scratched | 580.00 F | *580.00 F |

F=Franchise part.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$) | 3,410.00 | 2,266.00 |
| + Margin on L,N Items 10.00/10.00% (\$) | 341.00 | 226.60 |
| Total Parts (\$) | 3,751.00 | 2,492.60 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|---|----------|---------------------------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE AND REFIT FRONT BUMPER SENSOR | New | 100.00 | 60.00 |
| 2 | TO CHECK AND RECTIFY WIRING SYSTEM | New | 80.00 | 20.00 |
| 3 | TO PANEL BEAT AND STRAIGHTEN RH FRONT CHASSIS FRAME,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY,TO REFIT AND ADJUST THE SAME | New | 800.00 | 200.00 |
| 4 | TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS | New | 800.00 | 400.00 |
| 5 | TO RESET AND REPROGRAMME HEADLAMP FAULT-CODE *Check | New | 350.00 | 0.00 |
| | | | Gross Labour Cost (\$\$) | 2,130.00 |
| | | | | 680.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >