

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG21002851/UVF3Q2
Date: 15/03/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	80467309QMX
Claimant		
Vehicle No : SLJ6090E	Insured Vehicle No :	SJN3732J
Date of Loss: 02/03/2021	Nature of Claim: TP	Claim No: 634253

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ6090E		
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	CZDC21588
Reg. Date:	30/12/2020 (Man. Year: 2020)	Chassis No:	WAUZZZF36M1054631
Colour:	Black	Odometer:	3755 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65R17	Rear Tyre Size:	215/65R17
Front Left Side:	Falken 8 mm	Rear Left Side:	Falken 8 mm
Front Right Side:	Falken 8 mm	Rear Right Side:	Falken 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,567.00	4,494.10	17,072.90	79.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,780.00	1,780.00	2,000.00	52.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,347.00	6,274.10	19,072.90	75.25
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	25,347.00	5,000.00	20,347.00	80.27
+ GST 7.00/7.00% (S\$)	1,774.29	350.00	1,424.29	80.27
Nett Amount (S\$)	27,121.29	5,350.00	21,771.29	80.27

INSPECTION

Date of Assignment:	04/03/2021	
Date Inspected:	03/03/2021 Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 Mar 2021)
Parts: M1-SUV	AUDI Q3 SPORTBACK 1.4 TFSI S TRONIC (17) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ6090E)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Not Necessary	850.00 F	*- FL
2	1		*REAR WINDSCREEN MOULDING	Not Necessary	182.00 F	*- FL
3	1		*TAILGATE	Not Necessary	3,470.00 F	*- FL
4	1		*TAILGATE REAR LOGO	Not Necessary	108.00 F	*- FL
5	1		*TAILGATE INNER LOCK	Not Necessary	650.00 F	*- FL
6	1		*TAILGATE INNER TRIM BOARD	Not Necessary	688.00 F	*- FL
7	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 F	*- FL
8	1		*TAILGATE WEATHERSTRIP	Not Necessary	288.00 F	*- FL
9	1		*REAR BUMPER TOP	Deformed/Deep Cut	1,800.00 F	*1,634.00 FL
10	1		*REAR BUMPER LOWER SPORT	Deformed	2,080.00 F	*1,200.00 FL
11	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	230.00 F	*- FL
12	1		*SET REAR BUMPER CLIPS	Necessary	60.00 F	*60.00 FL
13	1		*REAR BUMPER REINFORCEMENT	Bent	788.00 F	*651.00 FL
14	1		*REAR BUMPER REINFORCEMENT RETAINER	Cracked	285.00 F	*85.00 FL
15	1		*REAR BUMPER PDC SENSORS (4 Pcs)	Shorted (2 Pcs only)	1,064.00 F	*488.00 FL
16	1		*SET REAR BUMPER PDC SENSOR WIRE	Not Necessary	350.00 F	*- FL
17	1		*REAR BUMPER TOP RETAINER	Cracked	299.00 F	*138.00 FL
18	1		*REAR END PANEL OUTER	Dented	850.00 F	*422.00 FL
19	1		*REAR END PANEL INNER	Repair	820.00 F	*- FL
20	1		*REAR END PANEL TOP GARNISH	Not Necessary	278.00 F	*- FL
21	2		*TAILLAMPS	Not Necessary	1,852.00 F	*- FL
22	2		*REAR FENDER INNER TRIMS	Not Necessary	1,772.00 F	*- FL
23	2		*REAR FENDER OUTER PROTECTORS	Not Necessary	798.00 F	*- FL
24	1		*REAR EXHAUST	Not Necessary	1,650.00 F	*- FL
25	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
26	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	50.00 FS	*- FS
27	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
28	1		*REAR LICENCE PLATE	Not Necessary	50.00 FS	*- FS
29	1		*TAILGATE Q3 EMBLEM	Not Necessary	105.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,567.00	4,728.00
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	233.90
Total Parts (\$\$)	21,567.00	4,494.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REAR PDC SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
4	TO TRANSFER TAILGATE MECHANISM	New	100.00	0.00
5	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	150.00	80.00
6	TO DISMANTLE & REFIX REAR EXHAUST	New	150.00	0.00
7	TO SPRAY RUST PROOFING	New	100.00	30.00
8	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,500.00	800.00
9	TO PUTTY & SPRAY PAINTING	New	1,500.00	800.00
Gross Labour Cost (\$\$)			3,780.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >