

ASS. REC. BY:

REF: C72/21002857/K4

MACH

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s

of

Insured: SKP7935S

Policy No. DMHCSNA00005852000

Claims No. SNM21D201177/C02/CHUAKK


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SFG 13134

Yr Regn: 08, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Bmw 520i

c.c. 1997

Colour: M. Black

A/C: Insured / Std / NI / NA

Sp. Reading: 137391

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA 5A 320200 333551

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD / Rlm or

Tyre Size: F: _____

R: 245/45ZR18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 2 mm

R/Bal. 2 mm

L/Bal. 2 mm

L/Bal. 2 mm

D.O.A. 27/2/21

D.O.I. 3/3/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
1	At GIA & EM not ready

lump sum \$3700, red: 12894.80;77%

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: 4

1)

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

Parking

Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$ 3700

Repair Estimate

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: BMW 520i
Engine/Chassis No.: WBA5A32020D333551
Date of accident:
Damaged area: Rear

Date: 08/03/2021
Claim Type: TP
VRN: SFG1313H



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Taillamp	2	\$ 954.00	\$ 1,908.00
2	Taillamp weatherseal	2	\$ 46.00	\$ 92.00
3	Taillamp panel	2	\$ 241.00	\$ 482.00
4	Rear bumper 1628	1	\$ 2,195.00	\$ 2,195.00
5	Rear bumper tow hook cover	1	\$ 59.00	\$ 59.00
6	Rear bumper side retainer	2	\$ 285.00	\$ 570.00
7	Rear bumper reinforcement 691-75	1	\$ 915.00	\$ 915.00
8	Rear bumper reinforcement bracket	2	\$ 211.00	\$ 422.00
9	Rear bumper upper bracket 180	1	\$ 382.00	\$ 382.00
10	Rear bumper lower bracket 185	1	\$ 449.00	\$ 449.00
11	Bootlid kick sensor 525	1	\$ 998.00	\$ 998.00
12	Bootlid kick sensor bracket 106	1	\$ 217.00	\$ 217.00
13	Rear bumper reflector	2	\$ 196.00	\$ 392.00
14	Rear bumper side cowl	2	\$ 281.00	\$ 562.00
15	Rear bumper center cowl 216	1	\$ 418.00	\$ 418.00
16	Rear bumper center chrome garnish 109-35	1	\$ 349.00	\$ 349.00
17	Rear bumper reflector chrome garnish	2	\$ 176.00	\$ 352.00
18	End panel	1	\$ 899.00	\$ 899.00
19	End panel top garnish	1	\$ 523.00	\$ 523.00
Subtotal				\$ 12,184.00
List discount				5.00%
Total				\$ 11,574.80

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Reverse sensor holder	4	\$ 38.00	\$ 152.00
2	Reverse sensor (Factory Original) 216	4	\$ 480.00	\$ 1,920.00
3	Taillamp panel sealant	1	\$ 100.00	\$ 100.00
4	Rear bumper clips	8	\$ 6.50	\$ 52.00
5	End panel top garnish clips	4	\$ 6.50	\$ 26.00
6	End panel sealant	1	\$ 120.00	\$ 120.00
7	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 2,420.00

Repair Estimate

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.5	\$ 100.00
3	Supply spray paint material and necessary items to respray affected area / panel.	5	\$ 1,000.00
4	To reset bootlid kick sensor mechanism.	1	\$ 200.00
5	To rust proof all affected portions after repair.	0.5	\$ ~ 100.00
6			
Total labour			\$ 2,600.00

3001

201

2801

801

X

Estimate Grand Total	\$ 16,594.80
----------------------	--------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: